Form 3160-5 (August 1999)

CI

INSTED CTATES

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CI HUDDV	NOTICES	AND	DEDUDTS	$\cap N$	WEI	18

Do not use this form for proposals to drill or to re-enter an 25 24 abandoned well. Use Form 3160-3 (APD) for such prosals.

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

			٠.	₩.	•	•••	•	٠	-
ς .	1 .	200	Ç.		1	Nia			

_		

iç (<u>Cont</u>	<u> 109</u>	

6.	If Indian,	Allottee	οг	T	T	ďr	e	ŀ	Jame

		(3)	Jicarilla Apache
IBMIT IN TRIPLICATE - Other Instruction	s Arrevense side	D B	7. If Unit or CA/Agreement, Name and/or N

ODBINI NA TRIL EIONTE - Guid Maddadin	E CEIVE	
. Type of Well Oil Well X Gas Well Other 2. Name of Operator	OIL CON DIV	8. Well Name and No. Jicarilla F 1
ENERGEN RESOURCES CORPORATION a. Address 2198 Bloomfield Highway, Farmington, NM 87401	3b. Phone No (include trea code)	9. API Well No. 30-039-06379 10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650 FSL, 990 FWL, Sec. 21, T26N, R5W, N.M.P.M.		S. Blanco PC
2000 102, 350 1112, 550. 22, 1201, 1011, 11111		11 County or Parish, State

CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12.

TYPE OF SUBMISSION		TYP	E OF ACTION	
Notice of Intent	Acidize	Deepen	Production (Start Resume)	Water Shut-Off
X Subsequent Report	Alter Casing X Casing Repair	Fracture Treat New Construction	Reclamation Recomplete	Well Integrity Other
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporanly Abundon	•
_	Convert to Injection	Plug Back	Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

8/3/01 MIRU.

8/6/01 ND wellhead, NU BOP. TOH laying down 1-1/4" tbg. Pick up 5-1/2" RBP. packer & 2-3/8" tubing.

8/7/01 Set RBP at 2910' and pressure test to 500 psi. Set packer at 2868 and test casing above packer to 625 psi for 30 minutes, no casing leak. TOH with packer. TIH with RBP retrieving tool.

8/8/01 Unload casing with N2. Latch onto RBP and TOH. TIH with 2-3/8" tubing and clean out to 3185'. TOH laying down 2-3/8" tubing. TIH with 123 jts 1-1/4" tubing, land at 3106'. ND BOP, NU wellhead. RDMO.

8/16/01 MIRU. ND wellhead, NU BOP. TOH laying down 1-1/4" tubing.

8/17/01 Pick up and TIH with 1-1/2" tubing, land at 3127'. ND BOP, NU wellhead.

8/20/01 RDMO.

14. Thereby certify that the foregoing is true and correct Name (Printed/Typed)	Title	
Don Graham	Production Superint	tendent
Now Archam	Date 9/25/01	
THIS SPACE FO	OR FEDERAL OR STATE OFFICE USE	
Approved by Conditions of approval, if any, are attached. Approval of this notice do	Title Demon En	Date 10 17 10,
Conditions of approval, if any, are attached. Approval of this notice decertify that the applicant holds legal or equitable title to those rights in which would entitle the applicant to conduct operations thereon.	oes not warrant or office A U F U	