Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED		
Budget Bur	eau No.	1004-0135
Expires:	March 3	11, 1993

5. Lease Designation and Serial No.

Jicarilla 99

SUNDRY NOTICES AND	HEPUR 13	ON	MELLO
--------------------	----------	----	-------

6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Jicarilla Apache Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well 8. Well Name and No. Oil Well X Gas 2 Jicarilla 99 2. Name of Operator MAR 1 6 ENERGEN RESOURCES CORPORATION 9. API Well No. 30-039-06492 3. Address and Telephone No. 10. Field and Pool, or exploratory Area 2198 Bloomfield Highway, Farmington, NM 87401 Gavilan PC/Blanco MV 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) DIST. 3 990 FNL, 990 FEL, Sec. 14, T26N, R3W, N.M.P.M. 11. County or Parish, State NM Rio Arriba CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Change of Pians Abandonment Notice of Intent **New Construction** Recompletion X Subsequent Report Non-Routine Fracturing Plugging Back Water Shut-Off Casing Repair Final Abandonment Notice Conversion to Injection Altering Casing Downhole Commingle Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled. give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* In accordance to NMOCD order DHC-2077, this well was downhole commingled as follows: 1/14/99 MIRU. TOH and laydown PC tubing string. Attempt to release seal assembly seal assembly stuck. 1/15/99 R.U. Wireline. Ran freepoint and cut off tubing at 5350'. Work tubing loose. TOH. TIH with 1/18/99 Clean out fill on top of seal assembly with air mist. Catch fish. Jar loose. TOH. TIH with packer milling assembly. 1/19/99 Mill out Model D packer at 5352'. TOH. TIH with 7 5/8" packer and RBP. 1/20/99 Test tubing - leak. TOH. TIH with packer set at 3257'. Test casing to 1000 psi-ok. TOH. 1/21/99 TIH with RBP set at 3912'. Set packer at 3745'. Test liner top to 1000 psi-ok. TOH. 1/22/99 TIH with bit. Tag fill at 5736'. SD for rig repair. 1/25/99 Clean out hard fill to 5985' with air mist. TOH. 1/26/99 TIH with packer set at 5362'. Acidize MV perfs with 1000 gals 15% HCL. TOH. TIH with packer and

4. I hereby certify that the foregoing is true and correct Signed	Title Production Superintendent	
(This space for Federal or State office (SS) Approved by Conditions of approval, if any:	Title Landa and Mineral Plesources	Date 11 5

1/27/99 Ran 190 jts. 2 3/8" 4.7# J-55 tubing set at 5901'. S. N. @ 5869'. Install single wellhead.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RBP. Acidize PC perfs with 500 gals 15% HCL. TOH.

Engineering Chart

Of

Subject _	JICARILLA 99#2)
000,000	NE/4 SEC 14, T26 N, R3W	

	10 3/4" 32.75 @ 302'
	~ 7 5/8" 24 to 4010'
PC PERPS 3672:3736'	Top of LINER @ 3860'
	2 ³ /8" 4.7 " @ 5901'
MV PRRF 5 5412'-5945'	51/2" 15.5" @ 6025'
VVV.	