5. LEASE

UNITED STATES

DEPARTMENT OF THE INTERIOR	<u> Jicarilla Apache 102 </u>
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
deocodione conte	Jicarilla Apache Tribe
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
on not use this form for proposals to drill or to deepen or plug back to a different servoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
servoir. Use form 9–331–C for such proposats./	Jicarilla Apacha 102
I. oil gas de other	9. WELL NO.
Well — Well	9. WELL NO.
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
AMOCO PRODUCTION COMPANY	Basin Dakota
B. ADDRESS OF OPERATOR 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
501 Airport Drive, Farmington, New Mexico	AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Section 10, T26N, R4W
below.) 1190' FNL x 1450' FEL, Section 10,	12. COUNTY OR PARISH 13. STATE
AT SURFACE: T26N R4W, Rio Arriba County, NM AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. AT 100.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REPORT, OR OTHER DATA	6857 KB
EQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	0397
EST WATER SHUT-OFF	
RACTURE TREAT	
HOOT OR ACIDIZE	F JUN
EPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
ULL OR ALTER CASING	
MULTIPLE COMPLETE LI LI HANGE ZONES	V CON COM
BANDON*	
other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is comeasured and true vertical depths for all markers and zones pertine. Having re-completed this well in the Gallup having re-completed this well in the Gallup having re-company was unable to drill out the baction. Successive attempts to do so have commediate vicinity of the bridge plug (7400°) the Dakota formation in this well by setting squeezing off with 100 sx Class "B" Neat cemes U.S.G.S. verbal approval received 4/23/80 per Subsurface Safety Valve: Manu. and Type	int to this work.)* norizon (7280'-7265'), Amoco Propridge plug isolating the Dakota caused severe casing damage in the Dakota a cement retainer at 7341' and ent. The telecon Schiller to Kuchera:
SIGNED B.E. Jachull TITLE DISTRICT ENG	ineer date April 29, 1980
(This space for Federal or State o	
APPROVED BY TITLE	DATE DESERVED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:	VESENTER LAND
ah & rut	JUI 1980
*Soo lostructions on Payerse	Side

NMOCC

