

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Caulkins Oil Company

3. ADDRESS OF OPERATOR
P.O. Box 780 Farmington, New Mexico

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' From North & 1120' From West
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE
NM 03551

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Breech E

9. WELL NO.
50 E

10. FIELD OR WILDCAT NAME
Blanco Mesa Verde Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 5 26 North 6 West

12. COUNTY OR PARISH 13. STATE
Rio Arriba New Mexico

14. API NO.
6572 Gr.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(other) _____

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8/28/82 Drilled to TD 7475'.
Attempted to run open hole logs, unsuccessful. Will run Gamma Ray Neutron Log when Completion Rig moves on.

Ran 5 1/2" 15.5 & 17# Casing as follows:

| | | | | |
|------------------|---------|------------------|------|------------|
| 7475' to 6516' | (959') | New 5 1/2" 17# | ST&C | J 55 Smls. |
| 6516' to 1023' | (5493') | New 5 1/2" 15.5# | ST&C | J 55 Smls. |
| 1023' to surface | (1023') | New 5 1/2" 17# | ST&C | J 55 Smls. |

Cemented first stage thru shoe at 7475' with 250 sacks (412.5 cu ft) 50 50 Poz, 6% Gel, 12 1/2# Gilsonite per sack followed by 100 sacks (118 cu ft) Neat. Plug down 6:10 AM 8/28/82

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Charles E. Veyna TITLE Superintendent DATE 8/31/82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOCC

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1976 O - 214-140

Cemented second stage thru stage tool at 5456' with 250 sacks (412.5 cu ft) 50 50 Poz; 6% Gel, 12 1/2# Gilsonite per sack followed by 100 sacks (118 cu ft) Neat. Plug down 7:35 AM 8/28/82.

Cemented third stage thru stage tool set at 3182' with 500 sacks (824 cu ft) 50 50 Poz, 6% Gel, 12 1/2# Gilsonite per sack followed by 100 sacks (118 cu ft) Neat. Plug down 9:10 AM 8/28/82.

Cemented circulated above both stage tools and to surface on third stage.

Stage tools set at: 5456' and 3182'.

Cement Baskets at: 5495' and 3268'.

Centralizers at: 7431, 7389, 7345, 7299, 7256, 7211, 7168, 7126, 7082, 7039, 6993, 6951, 6907, 6863, 6820, 6775, 5539, 5412, 5369, 5325, 5282, 5239, 5196, 3311 and 3138.