Form 3160-5 (November 1983)

UNITED STATES

SUBMIT	IN	TRIPL	ICA?	E.
(Other i		uctions	0 🖪	
verse side	()			

Form approved. Budget Bureau No. 1004-0 Expires August 31, 1985

DEPARTMENT OF THE INTERIOR 5. LEASE DESIGNATION AND SERVAL 50 (Formerly 9-331) <u>Jicarilla Contract 150</u> BUREAU OF LAND MANAGEMENT 6. IF INDIAN, ALLOTTES OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back the trevery to use "APPLICATION FOR PERMIT—" for such proposals. Jicari⊁1a Apache 7. UNIT AGREEMENT NAME JAN 14 1987 N/A WELL XIX OTHER 8 FARM OR LEASE NAME NAME OF OPERATOR BUREAU OF LAND MANAGEMENT JICARILLA G Union Texas Petroleum FARMINGTON RESOURCE AREA 9. WHLL NO. 3. ADDRESS OF OPERATOR 375 U.S. Highway 64, Farmington, New Mexico 87401

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT Blanco Mesaverde At surface 11. SEC., T., S., M., OR BLE. AND SURVEY OR AREA 925' FSL & 800' FEL Section 2-T26N-R5W
12. COUNTY OR PARISE | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14 PERMIT NO 6741 GL, 6753 KB Rio Arriba Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data SCREDGENT REPORT OF : NOTICE OF INTENTION TO REPAIRING WELL WATER SHUT-OFF PELL OR ALTER FISING TEST WATER SECT-OFF ALTERING CASING PRACTURE TREATMENT MULTIPLE COMPLETE PRACTURE TREAT SHOOTING OR ACIDIZING ABANDON SHOOT OR ACIDIZE prod. liner Int. csq., CHANGE PLANS Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) REPAIR WELL 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) *

Union Texas Petroleum wishes to advise that a 8-3/4" hole was drilled to 3720'. 7", 23#, K-55 casing was landed at 3720' and cemented to surface with 205 sxs (588 cu.ft.) 65/35 POZ containing 12% gel and 12-1/4# gilsonite/sk, tailed by 100 sxs (118 cu.ft.) Cl "B" with 2% CaCl2. Circulate 4 bbls (22 cu.ft.) of cement to surface. Nipple up BOP and test to 2500 psi - held OK. Drill 6-1/4"

hole with gas to 5950'. Run 4-1/2", 10.5#, J-55 production liner from 3388' to 5949'. Cement into intermediate casing with 260 sxs (408 cu.ft.) 50/50 POZ

containing 4% gel, 6-1/4# gilsonite/sk, and 10# salt/sk. Circulate 1 bbl (5 cu.ft.) of cement off of liner hanger.

ACCEPTED FOR RECORD JAN 1 5 1987 FARMINGTON RESOURCE AREA in . nereby certify that the foregoing is true and corpect DATE 01/09/1987 Permit Coordinator TITLE SIGNED This space for Federal or State office use) DATE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: