## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

l. <b>Type of Well</b> GAS	DECENTE	5. 6.	Lease Number Jic Contract 103 If Indian, All. or Tribe Name
SAS	NOV - 7 1995	7.	Jicarilla Apache Unit Agreement Name
2. Name of Operator	AMP COM	, <b>.</b>	onic rigicement wante
MERIDIAN ©IL		8.	Well Name & Number
<ol> <li>Address &amp; Phone No. of Operator</li> <li>PO Box 4289, Farmington, NM 874</li> </ol>	499 (505) 326-9700	9.	Jicarilla 103 #18 API Well No. 30-039-25536
4. Location of Well, Footage, Sec.,		10.	Field and Pool
1150'FSL, 1095'FWL, Sec.20, T-26-	-N, R-4-W, NMPM	11.	Basin Fruitland Coal County and State
			Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICAT	TE NATURE OF NOTICE. REPORT	r, other	DATA
Type of Submission	Type of Action	-,	
_X_ Notice of Intent		ge of Pla	
Subsequent Report	Plugging Back Non-I		Fracturing
Final Abandonment	Altering Casing Conve		o Injection
_X_	_ Other - Coring		
	<del>-</del>		
13. Describe Proposed or Completed  It is intended to perform side	d Operations		



## Jicarilla 103 #18

0.001.1110 100 #10	LOGGING SUPPLEMENT	
October 20, 1995	2000	MIC SOFFEEINEN
Fruitland Coal Asset Team r	request:	
Drilling Considerations:	Mud drilled hole	
performed on a da	e performed at the daily rate stands as the performed by Meridian. Require a stands are to be a standard to the performed by the performance	arting upon reaching the hi-resolution ed reaming of the hole, if any, shall be the hole is returned to correct
Hi-Resolution Mud Logging:	3260' - 3338'	
Mud Logging Service:	Rocky Mountain Geo. Engine Contact:	ering (970) 243-3044
Sidewall Coring:	60 - 1" cores @ 3260' - 3338'	
Sidewall Coring Service:	Schlumberger Contact: Jeff Gephart	(505) 325-5006
MOI Personnel: Geologist Drilling E		(505) 326-9764 (505) 326-9729
Prepared: G.W. Lee Drilling Engineer		J.C. Close Geologist
Reviewed:  Drilling Superintend	lent	
The state of the s		