Form 9-331 (May 1963)			
SUND (Do not use this fo	RY NOTICES AND REPOR	Plug back to a different reservoir. such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.  OIL X GAS WE'L X WELL OTHER  2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME  Carson Unit 8. Farm or Lease Name
Shell Oil Company 3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290			9. WELL NO. 44-24
4. LOCATION OF WELL (Rep See also space 17 below At surface	Bisti  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
660' FSL & 660' FEL Section 24			Section 24-T25N-R12W
14. PLRMIT No.	15. ELEVATIONS (Show whe 6464 KB	the: DF, RT, GE, etc.)	12. COUNTY OR PARISH 13. STATE  San Juan N. Mexico
16.	Check Appropriate Box To India	ate Nature of Notice, Report, or C	Other Data
SO	TICE OF INTENTION TO:	SUBSEQ	CENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT* X
SHOOT OR ACIDIZE	ABANDON*	(Other)	
REPAIR WELL (Other)		Nore: Report results	of multiple completion on Well letion Report and Log form.)
nent to this work.) *			al depths for all markers and zones perti-
	See atta	chment	
	APPROVE		
	1. V Refi€AT	·	
	ទី១១១៩៩ <b>ខ</b> ែឡុងភាពបាន		
	SUNDRY WHEN LOCATION DY FOR INSPECTION		
18. I hereby certify that t	te tyregoing is true and correct	Director Control Francisco	JUL 2 9 1977

SIGNED TITLE DIV. Opers. Engr. DATE (This space for Federal or State office use) DATE \_\_\_\_ APPROVED BY TITLU .... CONDITIONS OF APPROVAL, IF ANY: NEW MEXICO OIL CONSERVATION CORM.

cc: New Mexico O&GCC w/attachment1000 MO 3840 35 RD.

AZTEC, NEW MEXICO 87410 \*See Instructions on Reverse Side PLUG AND ABANDON WELL BISTI SHELL OIL COMPANY CARSON UNIT LEASE WELL NO. 44-24 WESTERN DIVISION ELEV 6464 KB 5/15-17/77 FROM: COUNTY SAN JUAN STATE NEW MEXICO

NEW MEXICO
BISTI FIELD
Carson Unit 44-24
(P&A)

"FR" TD 5025. AFE #528926 provides funds to plug and abandon well. 6/11 RU Bedford. Found tbg prt'd @ 1860'. Pulled tbg to look @ btm jt. Ran tbg back in to top of fish. Tried to screw into the tbg; able to do so, but tbg would pull apart. Pulled tbg again. Ran in overshot on tbg; got onto fish. Pulled all tbg string out of hole. Found collar on the fish was split. Ran tbg workstring back to tbg fish originally left in hole @ 4929. Loaded hole w/mud. Circ'd oil out of hole. 6/14 Spt'd 20 sx Class G cmt mixed w/1#/sx flocele over & above perfs. Pulled & LD tbg. RU hyd jacks.

Carson Unit 44-24 (P&A)

TD 5025. Shot off csg @ 1216 & spt'd 50 sx cmt plug across stub. Pulled csg to base of Ojo Alamc & spt'd 35 sx cmt plug. Pulled csg to base of 8-5/8' 165' & spt'd 25 sx cmt plug. Fin'd pull'g csg. RD Bedford 6/15/77. Prep to install sfc plug & abandonment marker.

Carson Unit 44-24 (P&A)

Ţ

TD 5025. 10 sx cmt plug at surface. Installed abandonment marker.
FINAL REPORT JUN 1 7 1977