



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe, N.M.
Lease No. F-078066
Unit Carbon

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Notice of Conversion to Injector	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 21, 1961

Carbon Unit
Well No. 32-24 is located 1980 ft. from N line and 1980 ft. from E line of sec. 24
SW NE 24 25 N. 12 E. N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Histi San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

Kelly Lushing
The elevation of the center floor above sea level is 6454.8 ft. New Mexico

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

- Y.D. 3010, 1000 5002'; casing 3-5/8" at 107', 4-1/2" at 5006'; Perfs. 4
1/2" holes/ft.) in intervals 4873-94, 4911-30, 4941-54, 4961-74,
4979-94.
1. Measure test tubing with 1000 psi for 15 min.
2. Pull tubing and bail clean.
3. Run 2-3/8" open-ended tubing to bottom and swab while running clean Point Look-
out water (treated with Triton X-100 detergent) down casing. When fluid cleans
up, pull tubing.
4. Run 2-3/8" tubing with packer ten feet above perforations.
5. Pump 60 bbls. of inhibited water down annulus to displace uninhibited fluid. Set
casing and fill with inhibited water.
6. Run pressure and temperature surveys as directed.

Company _____

Address _____

Original Signed By
W. M. MARSHALL

By _____
Title _____

