form 9-331 ('May 1963)	5. LEASE DESIGNATION E. W. Mudge SF 078064				
SUNDI (Do not use this for		6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
OIL GAS WELL Z WELL Z. NAME OF OPERATOR	Carson Unit	Carson Unit 8. Farm of Lease Name			
Shell Oil Compa	9. WILL NO.				
1700 Broadway, LOCATION OF WELL (Report of the low. At surface	Bisti	10. FIELD AND FOOL, OR WILDCAT Bisti			
660' FNL & 660'	SURVEY OR AREA	Section 24-T25N-R12W			
14. PERMIT NO.	15. ELEVATIONS (S	how whether DF, R	T, GR, etc.)	12. COUNTY OR PARISE	New Mexico
16.	Check Appropriate Box To		ture of Notice, Report, o		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIEE PROPOSED OR Concentration of the proposed work. If we nent to this work.) *	MULTIPLE COMPLETE ABANDON* CHANGE PLANS OMPLETED OPERATIONS (Clearly Streel is directionally drilled, give s		Completion or Reco details, and give pertinent da ns and measured and true ver	REPAIRING ALTERING C ABANDONME alts of multiple completion mpletion Report and Log for test, including estimated datical depths for all marker	on Well
18. I hereby certify fakt t)	or through to true and corpect			NOV 5 3/ OIL CO 1 30 DIST 3	. S ЭМ.
SIGNED	U. granel	TITLE DIV	Opers. Engr.	DATE _11/4	/75

TITLE _

DATE ___

WELL FILL	GGED AND ABANDONED		BISTI			
SMELL OIL COMPANY		LEASE	CARSON UNIT WELL NO			
FROM:	9/29 - 10/ 3 /75	DIVISION	WESTERN	ELEV	6438 KB	
			SAN JUAN	STATE	NEW MEXICO	
,						

NEW MEXICO BISTI FIELD

Carson Unit 11-24

"FR" TD 5015. AFE #415746 provides funds to P&A. MI Bedford Well Service. Spt'd rig & SD for weekend.
SEP 2 9 1975

Carson Unit 11-24

TD 5015. RU Bedford Well Serv. Attempted to pull rods; could not. RU HOT & circ'd hole. Well flwd back oil & gas until 2:30 p.m. RD HOT. Pulled & LD rods & pmp. SD SEP 30 1975 for night.

Carson Unit 11-24

TD 5015. PU 3 jts tbg & ran in & tagged btm @ approx 4893. Circ'd hole w/20 sx mud. Spc'd 20 sx mmt on bun. Pulled & LD 2-3/8 tbg. RU csg jacks & worked asg. Csg parted @ approx 600' below surface. Attempted in screw back into 4-1/2 csg collar, but could not. Shut crew down for night.

00T 01 1975

Carson Unit 11-24 TD 5015. Pulled & LD 396' 4-1/2 csg. Removed bad jt. Attempted to run back in the hole $w/4-1/2 \cos \delta$ fish parted collar, but could not. Pulled & LD 4-1/2 csg. PU & RIH w/2-3/8 tbg & worked tbg to 386'. Spt'd 55

sx cmt. Pulled tbg to 182'. Spt'd 35 sx cmt. Pulled remaining 2-3/8 tbg. Spt'd 10 sx cmt plug @ surface.

Carson Unit 11-24

TD 5015. RD&MO Bedford Well Service. Installed well marker & cleaned up location. Well P&A'd.

FINAL REPORT

OCT 03 1975