Form *=331 (May 1963)	DEPAR	SF 078064			
(Do not use	SUNDRY NO	TICES AND REPORTS  Obsals to drill or to deepen or plug CATION FOR PERMIT—" for such p	ON WELLS back to a different reservoir. proposals.)	6. IF INDIAN, ACLOTTEE OR TRIBE NAME	
OIL X W	AS OTHER	7. UNIT AGREEMENT NAME Carson_Unit			
2. NAME OF OPERATION Shell Oil				8. FARM OR LEASE NAME	
3. ADDRESS OF OPE	RATOR			9. WELL NO.	
1700 Broad	way, Denver	11-24			
4. LOCATION OF WE See also space I At surface	IL (Report location	Bisti			
660' FNL 8	660' FWL S	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  Section 24-T25N-R12W			
14. PERMIT NO.		15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE	
		6438' KB		San Juan New Mexic	
16.	Check	Appropriate Box To Indicate I	Nature of Notice, Report, or	Other Data	
	NOTICE OF INT	• •		QUENT REPORT OF:	
	NOTICE OF INI	Z.110.1 10.		·	
TEST WATER S	HUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TRE.	AT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACID	IZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL		(Other)(Note: Report result	ts of multiple completion on Well		
(Other)			Completion or Recom	pletion Report and Log form.)	
proposed wo nent to this v	rk. If well is dire	ctionally drilled, give subsurface loc	ations and measured and troe verte	s, including estimated date of starting any cal depths for all markers and zones perti-	
		See attachm	ent		
		O' Die . 3	NCV 6 1015		

\*See Instructions on Reverse Side

WELL PLUGGED AND ABANDONED	BISTI			
SHELL OIL COMPANY	LEASE	CARSON UNIT	WELL NO.	11-24
FROM: 9/29 - 10/3/75	DIVISION _	WESTERN	ELEV	6438 KB
FROM: 3/23 - 10/3//3	COUNTY	SAN JUAN	STATE	NEW MEXICO
i	·			

NEW MEXICO BISTI FIELD

Carson Unit 11-24

"FR" TD 5015. AFE #415746 provides funds to P&A. MI Bedford Well Service. Spt'd rig & SD for weekend. SEP 2 9 1975

Carson Unit 11-24

TD 5015. RU Bedford Well Serv. Attempted to pull rods; could not. RU HOT & circ'd hole. Well flwd back oil & gas until 2:30 p.m. RD HOT. Pulled & LD rcds & pmp. SD for night. SEP 30 1975

Carson Unit 11-24

TD 5015. PU 3 jts tbg & ran in & tagged btm @ approx 4093. Circ'd hole w/20 sx mud. Spt'd 20 sx ent on bun. Pulled & LD 2-3/8 tbg. RU csg jacks & worked csg. Csg parted @ approx 600' below surface. Attempted to screw back into 4-1/2 csg collar, but could not. Shut crew down for night.

Carson Unit 11-24

OOT 01 1975

TD 5015. Pulled & LD 396' 4-1/2 csg. Removed bad jt. Attempted to run back in the hole w/4-1/2 csg & fish parted collar, but could not. Pulled & LD 4-1/2 csg. PU & RIH w/2-3/8 tbg & worked tbg to 386'. Spt'd 55 sx cmt. Pulled tbg to 182'. Spt'd 35 sx cmt. Pulled remaining 2-3/8 tbg. Spt'd 10 sx cmt plug @ surface. SI well for night.

Carson Unit 11-24

TD 5015. RD&MO Bedford Well Service. Installed well marker & cleaned up location. Well P&A'd. FINAL REPORT

DCT 0.3 1975