

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 6597	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	Central Bisti Unit
3. Address of Operator	8. Farm or Lease Name
4. Location of Well	9. Well No.
UNIT LETTER <u>D</u> FEET FROM THE <u>N</u> LINE AND <u>660</u> FEET FROM THE <u>W</u> LINE, SECTION <u>16</u> TOWNSHIP <u>25N</u> RANGE <u>12W</u> NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
6252' KB	San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Return IA well to production	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was temporarily abandoned in February, 1965, because of a suspected csg. leak. We now propose to pump this well below a packer in an attempt to establish if a csg. leak repair can be justified.

1. M.I. & R.U. workover rig.
2. Run tbg. and setting into Model "D" Pkr at 4740.
3. Acidize w/500 gal HCL
4. Ran rods & pump.



16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>B.F. Brawley</u>	TITLE <u>District Engineer</u>	DATE <u>6-16-65</u>
APPROVED BY <u>Emory Clum</u>	TITLE <u>Superintendent #3</u>	DATE <u>6-14-65</u>
CONDITIONS OF APPROVAL, IF ANY:		