

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells

1. Type of Well Gas	5. Lease Number SF-078067
2. Name of Operator Central Resources, Inc.	6. If Indian, All. or Tribe Name
3. Address & Phone No. of Operator PO Box 1247 Bloomfield NM87413 (505) 632-3476	7. Unit Agreement Name Carson Unit
Location of Well, Footage, Sec., T, R, M 1910' FSL and 590' FWL, Sec. 11, T-25-N, R-12-W,	8. Well Name & Number Carson Unit 11 #13
	9. API Well No. 30-045-05475
	10. Field and Pool Fruitland PC
	11. County & State San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other -	

13. Describe Proposed or Completed Operations

Central Resources Plugged & Abandoned this well per the following:

- 1-19-99 MORU. Layout relief line to pit. Pressures: casing 40# and tubing 20#, bleed well down. NU BOP and test. Pump 25 bbls water down 1-1/4" tubing, circulate. Plug #1 with 32 sxs Class B cement from 1130' to 900' to fill perforations. TOH and LD 33 joints 1-1/4" tubing. WOC. Load casing with water and PT to 500#, held OK. Tag cement with wireline at 952'. Perforate 3 squeeze holes at 850'. Pump into holes with 2 bpm at 0#. Plug #2 with 51 sxs Class B cement pumped down 4-1/2" casing, squeeze 39 sxs outside casing from 850' to 750', displaced to 700', final pressure 750#. Shut in well and WOC.
- 1-20-99 Safety Meeting. Tag cement at 620' with wireline. Perforate 3 squeeze holes at 215'. Establish circulation out bradenhead. Plug #3 with 71 sxs Class B cement pumped down 4-1/2" casing from 215' to surface, circulate 1/2 bbl good cement. SI well and WOC. . Cut off wellhead, found cement at surface in both 4-1/2" casing and annulus. Mix 12 sxs Class B cement and install P&A marker. RD rig and equipment; MOL.
J. Morris, BLM representative was on location.

14. I hereby certify that the foregoing is true and correct.

Signed Rodney Z. Seale 2-13-99 Title District Manager Date 2/8/99

(This space for Federal or State Office use)
APPROVED BY _____ Title _____
CONDITION OF APPROVAL, if any: _____

ACCEPTED FOR RECORD

FEB 22 1999

NMOCD

FARMINGTON FIELD OFFICE
BY SW