Form	9 - 331
/ 31 a.v.	1002

16.

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY

14-20-603-323
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NO	DTICES	AND	REPORTS	ON	WELLS
-----------	--------	-----	---------	----	-------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir

Use "APPLICA"	TION FOR PERMIT—" for si	ich proposals.)			
OIL GAS GAS WELL OTHER	T PRINCIPLE	Ex Suche	7. UNIT AGREEMENT NA	AME	
2. NAME OF OPERATOR		10 To	8. FARM OR LEASE NAM	4E	
Hixon Development Com	pany		CBU		
3. ADDRESS OF OPERATOR		the Control of the Section 1	9. WELL NO.		
P.O. Box 2810, Farmir	gton, New Mexico	87401	9		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)			10. FIELD AND POOL, OR WILDCAT		
At surface			Bisti Lower G	allup	
Unit C, 1980' FSL, 660' FEL, Section 5, T25N, R12W			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
			Section 5, T2	5N, R12W	
14. PERMIT NO.	15. ELEVATIONS (Show wheth	er DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE	
	6167' DF		San Juan	NM	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:				
	Γ			ļ	r	
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	X	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		(Other)		
(Other) Return w	ell to	production	x	(Norg: Report results of m Completion or Recompletion	nultiple completion on Well Report and Log form	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is planned to return the subject shut in well to pump as follows:

- (1) Clean out to PBD
- (2) Acidize with 2000 gallons 15% acid
- (3) Hang on pump.



18. I hereby certify that the foregoing is true and correct	Lung Petroleum Engineer	DATE 10/7/80
(This space for Federal or State office use)		APPROVED
APPROVED BY	TITLE	L DATE
Complitions of Milliothi, if Mil.		~ 1000

*See Instructions on Reverse Side

TISTRICT OIL & GAS SUPERMISOR