UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved.

Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIAL NO.

ABANDON MENT*

GEOL	OGICAL	SURVEY
GEOL	.00.0	

MULTIPLE COMPLETE

CHANGE PLANS

QE 078565-A/

GEOLOGICAL SURVEY			6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			7. UNIT AGREEMENT NAME		
OIL GAS X OTHER			San Juan 28-7 Unit 8. FARM OR LEASE NAME		
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR BOX 990, Farmington, New Mexico 87401 4. Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1710'S, 1830'W			San Juan 28-7 Unit 9. WELL NO. 167 10. FIELD AND POOL, OR WILDCAT So. Blanco Pictured Cliffs Undesignated Chacra 11. SEC., T., B., M., OR BLE. AND SURVEY OR AREA Sec. 5, T-27-N, R-7-W NMPM		
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6751 GL			Rio Arriba New Mexico		
16. Check NOTICE OF IN TEST WATER SHUT-OFF	Appropriate Box To Indicate Notes Tention to: PULL OR ALTER CASING	nture of Notice, Report, o subs water shut-off fracture treatment	r Other Data SEQUENT REPORT OF: X REPAIRING WELL ALTERING CASING		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

12-16-73

Tested surface casing, held 600#/30 minutes.

12-29-73

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

Pictured Cliffs T.D. 3460'. Ran 115 joints 2 7/8", 6.4#, J-55 production casing, 3450' set at 3460'. Baffle set at 3450'. Cemented with 507 cu.ft. of cement. WOC 18 hours.

SHOOTING OR ACIDIZING



Chacra T.D. 4333'. Ran 141 joints 2 7/8", 6.4#, J-55 production casing, 4323' set at 4333'. Baffle set at 4323'. Cemented with 405 cu. ft. cement. WOC 18 hours. Top of cement at 1100'.

Pictured Cliffs PBTD 3450'. Tested casing to 4000#, O.K. Perfed Pictured Cliffs 3272-88', 3298-3310', 3338-50' with 16 SPZ. Frac'd with 52,000# 10/20 sand, 50,000 gallons water. Dropped 2 sets of 16 balls each. Flushed with 820 gallons water.

Chacra PBTD 4323'. Tested casing to 4000#, O.K. Perfed Chacra 4230-36', 4242-48', and 4276-82' with 9 SPZ. Frac'd with 19,500# 20/40 sand, 25,370 gallons water. Dropped 2 sets of 9 balls each.

No flush.				
18. I hereby certify that the foregoing is true and correct SIGNED . Decoco	TITLE _	Drilling Clerk	_ DATE	3-5-74
(This space for Federal or State office use)			DATE	
APPROVED BY	TITLE _		_ DATE	1 1 1 to

*See Instructions on Reverse Side

