Sundry	Notices and Reports on	Wells
1. Type of Well GAS		5. Lease Number SF-080675 6. If Indian, All.or Tribe Name
2. Operator Merilin El Paso Natural Gas Co		7. Unit Agreement Name San Juan 27-4 Unit 8. Farm or Lease Name
3. Address & Phone No. of PO Box 4289, Farmingt		San Juan 27-4 Unit 9. Well No. 87
4. Location of Well 1820'N, 1820'E	APR 0 3 1990 OIL CON. DIV.	<pre>10.Field,Pool, Wildcat    Tapacitos PC 11.Sec. T. R. M. or Blk    Sec.28,T-27-N,R-04-W    NMPM</pre>
14. Permit No.	15 Llevations 7097'GR	12.County 13. State Rio Arriba NM
16. Intent to/Subsequent	Report of : Repair We	11
psi. If pressure decline squeeze repaired by:  Mol ru. Kill sand plug acro Locate hole (sfailure. Open 18 hrs. Pick 775 psi. Resq	well as needed. Releass perfs. Tih w/pkr a) with packer. Shoot bradenhead and circul up drill pipe and dril ueeze if necessary. Ctrogen. Tooh. Tih w/	most current SICP of 666 minutes, the well will be see packer and tooh. Set nd test plug to 1500 psi. squeeze hole 20' below ate cement to surface. WOC lout cmt. Test squeeze to lean out sand plug and 1 1/4" production string
18. Authorized by: ${Regula}$	tory Affairs	/-22-90 Date
NOTE: This format is issu	ed in lieu of US BLM F	orm 3160-5
(This space for Federal o		Self Self (1) Elf Self (1) Elf (1)
APPROVED BY	TITLE	DATE
CONDITION OF APPROVAL, IF	ANY:	