				/		
form 9-331 (May 1963)				on re- 5. LEASE DESIGNATION AND SERIAL NO. SF 080670		
Sl (Do not use	JNDRY NO this form for propouse "APPLIC	TICES AND REPORTS (pages to drill or to deepen or plug beation for PERMIT—" for such p	ON WELLS pack to a different reservoir. roposals.)	6. IF INDIAN, ALLOTTEE OR	TRIBE NAME	
1.				7. UNIT AGREEMENT NAME		
OIL GAS X OTHER				San Juan 27-4 Unit		
2. NAME OF OPERATOR						
E1 Paso Natural Gas Company 3. ADDRESS OF OPERATOR				San Juan 27-4 Unit 9. WELL NO.		
P.O. Box 990, Farmington, New Mexico 87401 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  See also space 17 below.)				10. FIELD AND FOOL, OR WILDCAT		
At surface				Basin Dakota 11. sec., T., R., M., OR BLK. AND		
1550'S, 1720'W				SURVEY OR AREA Sec. 30, T-27-N, R-4-W		
				N.M.P.M.		
14. PERMIT NO.		15. ELEVATIONS (Show whether DE	F, RT, GR, etc.)	12. COUNTY OR PARISH 13.		
	<u> </u>	6730' GL		Rio Arriba  Ne	w Mexico	
16.	Check A	ppropriate Box To Indicate N	Nature of Notice, Report, or	Other Data		
NOTICE OF INTENTION TO:				QUENT REPORT OF:		
TEST WATER SH	UT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	X REPAIRING WELL		
FRACTURE TREAT	·	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	·	
SHOOT OR ACIDIZ		ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*		
REPAIR WELL (Other)	L	CHANGE PLANS	(Other)  (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
17 PROCEINE PROPOSI	ED OR COMPLETED OF	PERATIONS (Clearly state all pertiner tionally drilled, give subsurface loca	at datails and give pertinent date	s including estimated date of	starting any	
nent to this wo	rk.) *	dimed, give bubble and look			•	
5-26-74:	Spudded we	ll. Drilled surface	hole.			
5-27-74:	Cemented w	ts 9-5/8", 32.3#, H-4 ith 225 cu. ft. cemen d 600#/30 minutes.				
			÷ ;	***		
			# 27 	eslive e		
				JUN 5 BIN COM.		