UNITED STATES

DEPARTMENT OF THE INTERIOR RECEIVED BUREAU OF LAND MANAGEMENT

Sundry Notices and Report	36 9E We BI still 2: 16		
	070 FARMMGTON, NIM	5.	Lease Number
1. Type of Well GAS		6.	If Indian, All. or Tribe Name
		7.	Unit Agreement Name
2. Name of Operator MERIDIAN OIL			
		8.	San Juan 28-6 Unit Well Name & Number
3. Address & Phone No. of Operator		•	San Juan 28-6 U #205
PO Box 4289, Farmington, NM 87499 (505) 3	26-9700	9.	API Well No. 30-039-20850
4. Location of Well, Footage, Sec., T, R, M		10.	Field and Pool
1800'FNL, 1840'FEL, Sec.9, T-27-N, R-6-W, N	MPM		Basin Dakota
$\boldsymbol{\epsilon}$		11.	County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE O	F NOTICE, REPORT, C	THER	DATA
Type of Submission Ty	pe of Action		
X Notice of Intent Abandonme			
Recomplet	ion New Cons	truci	tion Fracturing ff
Subsequent Report Plugging Casing Re	pair — Non-Rout Pair Water Sh	ine i	fracturing ff
Final Abandonment Altering			o Injection
	asing clean out		
13. Describe Proposed or Completed Operation	s		
It is intended to clean out the casing i procedure and wellbore diagram.	n the subject well	acco	rding to the attached
			ECEINED
		b B	SEP 1 6 1996
			oci 1 6 1898 [6]
		\bigcirc Π	Lagran -
			L COM. DOV.
14. I hereby certify that the foregoing is t	rue and correct.		
Signed Shakhuld (ROS3) Title	Regulatory Administ	rato	r Date 9/5/96
(This space for Federal or State Office use) APPROVED BY	Dat	AE	PROVED
CONDITION OF APPROVAL, if any:			CED 1 0 1006
			SEP 1 0 1996

/S/ Duane W. Spencer DISTRICT MANAGER

San Juan 28-6 Unit #205 Basin Dakota NE Section 9, T-27-N, R-6-W Recommended Casing Cleanout Procedure

- 1. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. As much time as possible to the pump time is needed for the agency to be able to show up for the cement job.
- MOL and RU workover rig. Blow well down. NU 7-1/16" 3000 psi (6" 900 series) BOP with stripping head. Test and record operation of BOP rams. Kill well with 1% KCL water only if necessary. Have christmas tree serviced at A-1 Machine, if necessary.
- 3. Release donut and PU 1-1/2", 2.9#, tbg (235 jts @ 7369', SN @ 7347'). Pick up additional jts of tubing and check for fill by tagging bottom. TOOH. Visually inspect tubing for corrosion, replace as necessary. PU 4-1/2" casing scraper and RIH on 2-3/8" workstring, round-trip to 7400'.
- 4. TIH with 4-1/2" RBP and 4-1/2" packer on 2-3/8" workstring and set RBP at 7368' (50' above DK perfs). Pressure test RBP and 4-1/2" casing to 750 psig. If pressure test fails, isolate casing leak with 4-1/2" packer and contact Operations Engineer (Rob Stanfield 326-9715, Pager 324-2674) for cement squeeze procedure. Spot 10' of sand on RBP before pumping cement.
- 5. Unload hole with gas or air prior to retrieving bridge plug. TOOH with packer and RBP. PU 3-7/8" bit and TIH and CO to bottom with gas or air. TOOH. Check for scale build-up in tubing. Based on findings, discuss potential for acid treatment with Operations Engineer.
- 6. TIH with 1-1/2" tubing with a pump out plug on bottom and a seating nipple one joint off bottom. Rabbit all tubing. CO to COTD @ 7660' with gas or air. Take and record gauges.
- 7. Land tubing near bottom perforation at 7649'. ND BOP and NU wellhead. Pump off pump out plug and record final gauges. Return well to production.

Recommended:


ia o

San Juan 28-6 Unit #205

CURRENT

Basin Dakota

1800' FNL, 1840' FEL, NE Section 9, T-27-N, R-06-W, Rio Arriba County, NM Latitude/Longtitude: 36.590851 / 107.468887



Initial Potential		Production History	<u>Gas</u>	<u>Oil</u>	<u>Ownership</u>		<u>Pipeline</u>	
Initial AOF: Current SICP:	N/A 936 psig	(3/92)	Cumulative: Current:	920.8 MMcf 82.7 Mcfd	5.0 Mbo 1.0 bbls/d	GWI: NRI: TRUST:	56.56% 46.14% 00.00%	EPNG