							/	
Form 9-331 (May 1963)		UNITED STATES	,	SUBMIT IN TRIPLICAT	E•	Form approv Budget Bures	d. 1u No. 42-R1424.	
(May 1963)	DEPARTI	MENT OF THE I	NTERIOR	R (Other instructions on re-		5. LEASE DENIGNATION AND SERIAL NO.		
GEOLOGICAL SURVEY					S	SF080669 /		
	UNIDDY NOT	ICES AND REPO	DTC ON	\M/ELLC	6.	IF INDIAN, ALLOTTE	C OR TRIBE NAME	
(Do not use	this form for propos Use "APPLICA	sals to drill or to deepen ATION FOR PERMIT—" for	or plug back to or such propose	o a different reservoir.				
					7. UNIT AGREEMENT NAME			
OIL GAS TO OTHER						San Juan 27-4 Unit		
2. NAME OF OPERATOR						8. FARM OR LEASE NAME		
El Paso Natural Gas Company						San Juan 27-4 Unit		
3. ADDRESS OF OPERATOR						9. WELL NO.		
P. O. Box 990, Farmington, NM 87401						74		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.						10. FIELD AND POOL, OR WILDCAT		
At surface	,			the same whether the same of t		apacito PC I		
					- 1	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
810'S, 1125'E						Sec. 17, T-27-N, R-4-W		
		(0)				.M.P.M.	1 12 amire	
14. PERMIT NO. 15. ELEVATIONS (Show wheth			hether DF, RT, (R, etc.)	,		1	
		7175'GL			, [K	io Arriba	New Mexico	
16.	Check A	ppropriate Box To Ind	icate Natur	e of Notice, Report, o	r Othe	r Data		
NOTICE OF INTENTION TO:					UBSEQUENT REPORT OF:			
TEST WATER SH	UT-OFF	PULL OR ALTER CASING	7	WATER SHUT-OFF	χ	REPAIRING '	WELL	
FRACTURE TREAT		MULTIPLE COMPLETE	_	FRACTURE TREATMENT		ALTERING C	ASING	
SHOOT OR ACIDI	[]	ABANDON*		SHOOTING OR ACIDIZING		ABANDONME	NT*	
	REPAIR WELL CHANGE PLANS (Other)							
(Other)	(Note: Report results						on Well	
17. DESCRIBE PROPOS proposed work nent to this wo	. If well is direction	ERATIONS (Clearly state all onally drilled, give subsur	pertinent det face locations	ails, and give pertinent da and measured and true ver	tes, incl	uding estimated dat pths for all marker	te of starting any s and zones perti-	
11-05-74	Spudded we	11. Drilled sur	rface hol	e.			-	
11-06-74	Ran 10 join	its 8 5/8", 24# 3	J-55 surf Circulat	Eace casing, 320 ted to surface.	set WOC	at 332'. (Cemented eld 600#/	

St