

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

11. County or Parish, and State
RIO ARriba COUNTY, NM

Date 11/08/2001

OFFICE

Additional data for EC transaction #7995 that would not fit on the form

32. Additional remarks, continued

3431'. Establish injection. Plug #6: pump 65 sx Class "B" neat cmt outside 7" csg @ 2920-3480'. Pump 42 sx Class "B" neat cmt inside csg above cmt retainer @ 2863-3431'. TOOH. TIH. Perf 4 sqz holes @ 1786'. TOOH. TIH w/4 1/2" cmt retainer, set @ 1732'. Establish injection into sqz holes. Plug #7: pump 45 sx Class "B" neat cmt outside csg below cmt retainer @ 1686-1786'. Pump 7 sx Class "B" neat cmt inside csg above cmt retainer 1636-1732'. TOOH. TIH. Perf 3 sqz holes @ 271'. Establish circ down annulus & out bradenhead. SDON.
10-11-01 Establish circ down annulus & out bradenhead. Plug #8: pump 107 sx Class "B" neat cmt down 4 1/2" csg & out bradenhead. Circ 5 sx cmt out 4 1/2" csg & bradenhead. ND BOP. Cut off WH. Cmt fell 6' inside csg & 8' in annulus. Pump 25 sx Class "B" neat cmt to fill csg & annulus. Install dry hole marker w/5 sx Class "B" neat cmt. RD. Rig released.

Well plugged and abandoned 10-11-01