

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
SF 078000

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Huerfano Unit
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Huerfano Unit
3. Address of Operator P. O. Box 990, Farmington, New Mexico 87401	9. Well No. 143
4. Location of Well UNIT LETTER <u>J</u> <u>1650</u> FEET FROM THE <u>south</u> LINE AND <u>1650</u> FEET FROM THE <u>east</u> LINE, SECTION <u>9</u> TOWNSHIP <u>26N</u> RANGE <u>9W</u> NMPM.	10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 6401' GL	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Due to a possible casing failure the following work is being proposed for the subject well:

1. Pick up tubing from Howco E-Z drill retainer.
2. Circulate 68 Bbls of Baroid casing packer fluid in annulus displacing the tubing with 10 Bbls of diesel and 15 Bbls of water.
3. Set tubing back in Howco E-Z drill retainer.
4. Swab well back on production.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *A. R. Kendrick* TITLE Production Engineer DATE August 19, 1975

Original Signed by A. R. Kendrick PETROLEUM ENGINEER DIST. NO. 5 DATE AUG 20 1975

APPROVED BY _____ CONDITIONS OF APPROVAL, IF ANY: