

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR JEROME P. McHUGH	8. FARM OR LEASE NAME Bengal A
3. ADDRESS OF OPERATOR P O Box 809, Farmington, NM 87499	9. WELL NO. 4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 790' FNL - 1850' FWL	10. FIELD AND POOL, OR WILDCAT South Gallegos Fruitland PC
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T26N, R12W, NMPM
15. ELEVATIONS (Show whether on or off the resource area) 5987'	12. COUNTY OR PARISH San Juan
	13. STATE NM

RECEIVED

JUN 05 1987

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

XX

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Rigged up and perforated 1356' to 1360' with 2 shots per foot (8 holes).  
Acidized with 100 gal. of 15% HCL.  
Swabbed well, unable to flow or test.

Due to non-economical productivity, plan to plug and abandon well as follows:

Rig up on 2-7/8" casing and pump 40 sx of Class "B" cement (47.2 cu.ft.) to plug well from bottom perf at 1360' to surface.

Cut off casing below ground level and install dry hole marker.

Restore surface in accordance with instructions from the Surface Management Agency.

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

RECEIVED

JUN - 9 1987

OR. CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

James S. Hazen

TITLE

Field Supt.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE 6/1/87

JUN 08 1987

for AREA MANAGER  
FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side

NMOC