



# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT

Farmington Field Office  
1235 La Plata Highway, Suite A  
Farmington, New Mexico 87401

IN REPLY REFER TO:  
NMNM 013492, et al.  
3162.3-1 (07100)

JUN - 6



Maralex Resources  
PO Box 338  
Ignacio, CO 81137

Gentlemen:

Enclosed are your Applications for Permit to Drill (APD) for the following wells:

1. No. 1 W. Bisti 26-13-19, NENE  $\frac{1}{4}$  Sec. 19, T. 26N, R. 13W, San Juan County, New Mexico, lease NMNM 013492. *30-045-29104*
2. No. 2 W. Bisti 26-13-18, SESW  $\frac{1}{4}$  Sec. 18, T. 26N, R. 13W, San Juan County, New Mexico, lease NMNM 013492. *30-045-29103*
3. No. 2 W. Bisti 26-13-19, SWSW  $\frac{1}{4}$  Sec. 19, T. 26N, R. 13W, San Juan County, New Mexico, lease NMNM 013492. *30-045-29087*
4. No. 2 W. Bisti 26-13-17, NESW  $\frac{1}{4}$  Sec. 17, T. 26N, R. 13W, San Juan County, New Mexico, lease NMNM 013492. *30-045-29120*

The subject APD is rescinded and returned due to drilling not being commenced within the time frame authorized by either APD's or extensions of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Matthew Warren  
Petroleum Engineer,  
Petroleum Management Team

4 Enclosures

cc:  
/ NMOCD, Aztec, NM