

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla Tribal Contr. 241

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Boulder

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Boulder Mandos

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 23, T28N, RIW

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mex.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Workover

2. NAME OF OPERATOR

Tesoro Petroleum Corporation

3. ADDRESS OF OPERATOR

1776 Lincoln St., Suite 1012, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

330' FNL & 1650' FNL

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, CR, etc.)

GL 7195'; KB 7206'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. WIH w/jet casing cutter and cut off liner at 3678'. Attempted to pull liner, unable to pull same.
2. WIH w/ jet casing cutter and cut off liner at 3300'. Pulled 298' of 4 1/2" 9.5#/ft. slotted liner and 4' liner hanger.
3. After pulling the upper 302' of liner and hanger, hole sloughed.
4. RU cable tool rig and cleaned out open hole from 3041' (7" csg shoe) to 3305' (T/4 1/2" cut off) w/5 1/2" tools.
5. Attempted to fish remaining 4 1/2" liner w/cable tool rig, unable retrieve same.
6. RU pulling unit and attempted to retrieve liner. Pulled remaining liner up the hole 12' to 3293' GL but was unable to retrieve same.
7. Temporarily abandoned well; awaiting further evaluation before resuming operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

L. Charles Marquart

TITLE L. Charles Marquart

DATE 10/9/74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: