

30-045-28049

07-31-90

F

F. Loc. 790/S; 990/W Elev. 5907 GL Spd. Cu. ft. ID. Cu. ft. PB
@ W Sx. Int. @ W Sx. Pr. @ W Sx. I. @
sg Perf. Prod. Slim.

T Gas
R
A
N
S

BO/D MCF/D After Hrs. SSCP PSI After Days GOR Grav. 1st Del. Gas
1st Del. Oil

TOPS		NitD	X	Well Log	TEST DATA								
Ojo Alamo		C-103		Plot	X					Schd.	PC	Q	PW
Kirland		C-104		Electric Log									
Fruitland				C-122									
Pictured Cliffs		Ditr		Dfa									
Chacra		Dair		Dac									
Cliff House													
Menefee													
Point Lookout													
Mancos													
Gallup													
Greenhorn													
Dakota													
Entrada													
					Acres W/320								

P
o
o

BasinFrCoal Co. SJ S 31 T 27N R 12W UM Oper. Merrion Oil & Gas Corp. Morgan

No. 5



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO

NM-33047 et al. (WC)
3162.3-1 (019)

Merrion Oil & Gas Corporation
P.O. Box 840
Farmington, NM 87499

OCT. 10 1991

RECEIVED
OCT 11 1991
OIL CON. DIV
DIST. 3

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 5 Hi Roll, sec. 35, T. 27 N., R. 13 W., San Juan Co., NM, lease NM-33047.
- ✓ 2. 2 Nelson, sec. 9, T. 26 N., R. 12 W., San Juan Co., NM, lease SF-078944-A.
3. 11 Southland, sec. 9, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-12235.
- ✓ 4. 8 Southland, sec. 10, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-12235.
5. 1 Star Federal 30, sec. 30, T. 26 N., R. 12 W., San Juan Co., NM, lease NM-0560223.
- ✓ 6. 5 Morgan, sec. 31, T. 27 N., R. 12 W., San Juan Co., NM, lease SF-080238-A.
- ✓ 7. 7 Delhi Taylor A, sec. 17, T. 26 N., R. 11 W., San Juan Co., NM, lease SF-079679.
8. 2 Frontier, sec. 5, T. 26 N., R. 12 W., San Juan Co., NM, lease SF-081102-A.
9. 9 Southland, sec. 11, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-12235.
10. 10 Southland, sec. 3, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-12235.
- ✓ 11. 2 Serendipity, sec. 26, T. 26 N., R. 13 W., San Juan Co., NM, lease NM-33031.

As discussed with Steven Dunn of your company on, October 8, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410