

N

30-045-28204

09-14-90

F. Loc. 870/N: 1510/E Elev. 5900 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del Gas _____
 MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del Oil _____

TOPS		NIID	Well Log	TEST DATA							Ref. No.
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
		Acres E/320									

P
o
o

BasinFrCoal Co. SJ S 12 T27N R 09W U B Oper. Texaco E & P Inc. Lse. Charley Pah No. 5

Charley Pah #5

B-12-27N-09W

Texaco E & P Inc.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO
SF-078357-A et al. (WC)
3162.3-1 (019)

OCT. 1 2 1991

Texaco Inc.
3300 N. Butler
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 4 J. Q. Marshall, sec. 1, T. 27 N., R. 9 W., San Juan County, NM, lease SF-078357-A.
- ✓ 2. 4 H. J. Loe Federal B, sec. 23, T. 29 N., R. 12 W., San Juan County, NM, lease NM-014378.
- ✓ 3. 8 Nellie Platero, sec. 10, T. 27 N., R. 9 W., San Juan County, NM, lease I-149-IND-8464.
- ✓ 4. 10 John Charles, sec. 13, T. 27 N., R. 9 W., San Juan County, NM, lease I-149-IND-8466.
- ✓ 5. 5 Charley Pah, sec. 12, T. 27 N., R. 9 W., San Juan County, NM, lease I-149-IND-8465.
- ✓ 6. 3 Neah Victoria, sec. 1, T. 27 N., R. 9 W., San Juan County, NM, lease I-149-IND-8463.

As discussed with Mark Wakefield of your company on, October 11, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller
Chief, Branch of Mineral Resources

6 Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410
BIA, Window Rock

ABANDONED LOCATION

RECEIVED

OCT 21 1991

OIL CON. DIV
DIST. 3