Form 9-331 Dec. 1973

oil

well

below.)

REPAIR WELL

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

other

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

AT SURFACE: 1180 N, 1460 E, SEC 20, T28N, R9W

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,

O Box 289, Farmington, NM 87401

gas

well

料

El Paso Natural Gas Co.

AT TOP PROD. INTERVAL: a/a AT TOTAL DEPTH: a/a

REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON*

5. LEASE SF077106
31077100
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Lackey B
9. WELL NO. 16
10. FIELD OR WILDCAT NAME Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY O
NE SEC. 20, T28N, R9W
12. COUNTY OR PARISH 13. STATE
San Juan New Mexic
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WE

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

5922 DF

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SUBSEQUENT REPORT OF:

A Guiberson Unipacker VI was set in this well on Oct. 9, 1979, at which time a request to evaluate this well for a period of 90 days was granted.

Because of freezes in wellhead equipment, poor roads and excessive water problems, it is felt that this well has not been thoroughly evaluated. The excessive water problems have only recently been rectified and it is requested that an additional 90 days be granted to evaluate this well.