

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

EXPIRES AUGUST 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

3. LEASE DESIGNATION AND SERIAL NO
Jicarilla Tribal 454A

6. IF INDIAN, ALLIANCE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla Tribal 454A

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undes. Gallup

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

NW/SW Sec 24, T29N, R3W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Amoco Production Co.

3. ADDRESS OF OPERATOR

2325 E. 30 St., Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface:

1650' FSL x 790' FWL

RECEIVED

DEC 17 1986

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, GR, etc.)

6983' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PLUG OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Amoco Production Company requests approval to plug and abandon the subject well according to the attached procedure.

RECEIVED
DEC 18 1986
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

AS Shaw

TITLE Adm. Supervisor

DATE 12-11-86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

DEC 17 1986

John Skellin
AREA MANAGER

*See Instructions on Reverse Side

FARMINGTON DISTRICT
COMPLETION PROCEDURE

Date: 12/9/86

WELL NAME: JICARILLA THERMAL 454A #1 FIELD: WILDCAT

LOCATION: 1650' FS, 790' FWL, SEC 24, T29N R3W FORMATION(S): GALLUP

TRIO AREA CO., NEW MEXICO

ELEVATIONS: KB: 6996' TD: 8299' PBD: 7998'

CASING: 13 5/8" 45# H-90 CSA 300'

5 1/2" 155 17# K-55 CSA 8299'


LOGS: DL-SP-GR; FDL-CNL-GR; PROXIMICRLOG; GNC-LSS

DV TOOL SET AT: 6183'

PURPOSE: PLUG AND ABANDONMENT

DBB 2 TWE GOM MCH RWO/AJM 2DF 2D ENGR FILE
BJW RGH BVD GMK

WELLBORE SKETCH



PROCEDURE

- ① MICROSO. 20' WELLHEAD; 20' BOP'S.
- ② TOH LAYING DOWN TBL.
- ③ SPOT 12 SX CLASS B CMT ACROSS TOP OF GALLUP (6150' - 6250').
- ④ SPOT 12 SX CLASS B CMT ACROSS TOP OF MESAVENDE (5550' - 5650').
- ⑤ SPOT 12 SX CLASS B CMT ACROSS TOP OF PICTURED CLIFFS (3400' - 3500').
- ⑥ SPOT 12 SX CLASS B CMT ACROSS TOP OF FRUITLAND (3200' - 3300').
- ⑦ SPOT 12 SX CLASS B CMT ACROSS TOP OF OLD MAMMO (3000' - 3100').
- ⑧ SPOT 45 SX CLASS G + 2% CaCl₂ FROM 400' TO SURFACE.
- ⑨ ERECT DRY HOLE MARKER AND RECLAIM LOCATION AS REQUIRED.

DISTRICT MANAGER [Signature]

DISTRICT ENGINEER [Signature]

DISTRICT DRILLING SUPERVISOR [Signature]

ENGINEER DAVE DELVENTHAL

DATE 12/9/86