


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Havaio _____
Allottee _____
Lease No. 1-89-IND-57



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

Convert to Water

Injection Well (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 25 is located 1980 ft. from S line and 1980 ft. from W line of sec. 34
SW/4 Sec. 34 T28N R17W BMFM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Table Mesa San Juan County New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5341 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Refer to well history dated 9-19-62. This well has been shut-in pending study of pressure maintenance of the Dakota reservoir and our application to the New Mexico Oil Conservation Commission for authority to conduct a pressure maintenance program. On September 11, 1963, the NMOC granted our application with Order No. R-2564. Table Mesa No. 25 will be used as the key water injection well. Produced water will be injected down the casing. No remedial work is necessary to convert this well to water injection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company Continental Oil Company

Address Box 3312

Durango, Colorado

By A. J. Haley

Title District Manager



1. The first step in the process is to identify the problem. This involves gathering information about the situation and the people involved.