Form 9-331 UNITED STATES	SUBMIT IN TRIPLICATE*	Form approved.
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	OR (Other instructions on reverse side)	5. LEASE DESIGNATION AND SERIAL NO. 24-20-603-2013
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Use "APPLICATION FOR PERMIT—" for such pro	pposals.)	Navajo Tribal
OIL GAS WELL OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
Skelly Dil Company 3. Address of Operator		Navelo Na
Box 730 - Hobbs, New Mexico		9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT
		Gallup Wildeat 11. SEC., T., R., M., OR BLK. AND
		SURVEY OR AREA
660' FSL & 1980' FWL Sec. 23-28N-15W		Sec. 23-281-15%
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5570 DF		12. COUNTY OR PARISH 13. STATE San Juan New Mexic
16. Check Appropriate Box To Indicate No	sture of Notice Person on O	AL D-A
NOTICE OF INTENTION TO:		iner Data Ent report of:
		1
FRACTURE TREAT PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING
8HOOT OR ACIDIZE ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL CHANGE PLANS	(Other)	
(Other)	Completion or Recomple	of multiple completion on Well tion Report and Log form.)
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent proposed work. If well is directionally drilled, give subsurface locationent to this work.)* 	details, and give pertinent dates, in and mensured and true vertical	including estimated date of starting any depths for all markers and zones perti-
Well Plugged and Abandoned in the following	g memner:	[일 : 이웃] 최 - 홍 형 모듈 등 황
1. Moved in and rigged up casing puller.		
2. Eilled well with mud.		
3. Spotted 10 sack cement plug from 4600' to 4494'.		
4. Pulled tubing.		DECEMENT
5. Ran Free Point Indicator.		RECEIVED
6. Shot off 4-1/2" OD casing at 3462' and pulled casing. 7. Spotted 25 sack cement plug from 3503' to 3383'.		
8. Spotted 25 sack cement plug from 1407' to 1317'.		JAN 12 1956
Q. Smottad 25 anch coment nive from 5501 to	1.601	
10. Spotted 10 sack ceasest cap in top of sur	rface casing and inst	U-S GEOLOGICAL QURVEY
dry hole marker.	,	
11. All intervals not cemented are filled with 12. Plugging operations were completed on Ja	ion nor vy mia Laden i	luid.
man small miner and and a south round out at	minus of Those	CELLINE!
Note: Please return approved copy to the a	ove address.	/KIPLIATE /
		JAN 1 3 1966
	196	JAN 1 3 100
	e e e	OIL CON. COM.
18. I hereby certify that the foregoing is true and correct	st. Superintendent	
SIGNED (SIGNED) M. S. AGO TITLE	rao ander ture mineur	Jan. 17, 1966
(This space for Federal or State office use)		
APPROVED BY TITLE	4.	DATE
CONDITIONS OF APPROVAL, IF ANY:		
		그 요그는 사용을 필요하다.

*See Instructions on Reverse Side

XERO

XERO

XERO

XERO