

Santa Fe


Land Office

Lease No. **SM 013365**

Unit

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	☒	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	1959
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. **2** is located **860** ft. from **XIX** line and **1050** ft. from **E** line of sec. **22**
SE/4 SE/4 **T28N** **R 11 W** **N19M**
(Field) (Twp.) (Range) (Meridian)
Midland **San Juan** **New Mexico**
(County or Subdivision) (State or Territory)

The elevation of the **Ground** ~~surface~~ above sea level is **5608** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill - 13-3/8" Hole to 250'
Set 9-5/8" 32.30# csg. Cement with 150 sz cement.
Drill 7-7/8" hole to 6390' to test Dakota Formation
Set 5 1/2" 15 1/2# csg. at T. D. cement with 300 sz cement,
Perforate Dakota fm, Selective water- ed. frac fm.
Cleanout to T. D. run tbg and complete well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Redfern & Hord**

Address **P. O. Box 1747**

Midland, Texas

By **Original signed by T. A. Dugan**
Title **Consulting Engineer**