

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-077976

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> Dual well	7. UNIT AGREEMENT NAME Southeast Cha Cha
2. NAME OF OPERATOR Suburban Propane Gas Company	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR P. O. Box 1980, Farmington, New Mexico 87401	9. WELL NO. 26 (Formerly ENG Jones 1)
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' FSL, 790' FEL Unit P	10. FIELD AND POOL, OR WILDCAT Cha Cha Gallup & Dakato
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 17 T28N R-13W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6026KB	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING


ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In order to increase production on the above well in the Dakato Zone, we propose to workover this well as follows:

1. Move in pulling unit, pull tubing and Gallup packer.
2. Run 2 3/8" tubing with stinger and sting back in model "D" Baker packer.
3. Swab well and test.
4. If well comes around, put back on production for lease use.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Superintendent of Rocky Mountain area

DATE 10-13-78

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

akaf

Nmocc