

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

S-F-077976

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Southeast Cha Cha

8. FARM OR LEASE NAME

9. WELL NO.

26 (formerly BMG Jones 1)

10. FIELD AND POOL, OR WILDCAT

Cha Cha Gallup & Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 17, T28N R-13W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☒ GAS ☒ OTHER ☐ Well
WELL WELL

2. NAME OF OPERATOR
Suburban Propane Company

3. ADDRESS OF OPERATOR
P. O. Box 1980, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

790' FSL, 790' FEL unit P

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6056 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Test Dakota

REPAIRING WELL



ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Moved unit to well and rigged up. Pulled and layed down 1½" tubing, that parted, fish out rest of 1½" tubing to top of Gallup packer, milled out packer, and pulled rest of 1½" tubing to Dakota packer. Milled out Dakota packer and fish out 1½" tubing below packer, clean out to T. D.
- Ran 192 joints of 2 3/8" tubing with a A.D. 1 Baker packer land at 6198.75. Swab well, would not come around.
- Set pump jack, and ran 230 3/4 rod with pump. Pump well for 4 weeks, made all water and no gas. Shut well in. T. B.
- Tested well for packer test, no pressure on tubing and 162 on back side down in 15 min. No pressure on either side.



18. I hereby certify that the foregoing is true and correct

SIGNED

Donald L. Miller

TITLE

Superintendent of
Hocky Mountain area

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

nmocc