

wellfile



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410

LAND COMMISSIONER
PHIL R. LUCERO

DIRECTOR
JOE D. RAMEY



STATE GEOLOGIST
EMERY C. ARNOLD

July 20, 1976

Mr. Donald Miller
Bird Oil Company of Oklahoma, Ltd.
3101. Knudsen
Farmington, New Mexico 87401

Re: Bird Oil Company of Oklahoma, Ltd.
Southeast Cha Cha Unit #27
N-16-28N-13W

Dear Mr. Miller:

The attached Bradenhead Test Report received here July 19, 1976, indicates that the casing has failed in the subject well.

Rule 108 requires that the operator of a well with defective casing shall proceed with diligence to repair the well or to plug and abandon the well.

File form 9-331 showing the intended action prior to any field action for this repair.

If there are questions, please contact us.

Yours very truly,

A. R. Kendrick
A. R. Kendrick
Supervisor, District #3

ARK:mc

Attach.

xc w/ attach: Oil Conservation Commission
Santa Fe, New Mexico

United States Geological Survey
Farmington, New Mexico

NEW MEXICO OIL CONSERVATION COMMISSION
1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT
(Submit 3 copies to above address)

2

Date of Test 6-21-76 Operator BIRD OIL CO.

Lease Name S.E. CHA-CHA Well No. 27 Location U N Sec. 16 Twp. 28N Rge. 13W

Pressure (~~Shut-in or Flowing~~) Dwt. 310 Tubing 260 Casing 260 Bradenhead 182
PUMPING

OPEN BRADENHEAD TO ATMOSPHERE FOR 15 MINUTES.

Casing or Tubing Pressure, Dwt.

Bradenhead Flowed:

5 Min. 280

Steady Flow _____

10 Min. 240

Surges ✓

15 Min. 258

Down to Nothing _____

20 Min. 240

Nothing _____

25 Min. _____

Gas + OIL ✓

30 Min. _____

Gas & Water _____

Water _____

If Bradenhead flowed water check description below:

Clear _____

Fresh _____

Salty _____

Sulfur _____

Black _____

Remarks: EST. 6 BBLs OF

OIL IN 20 MIN. CASING

PRESSURE CLIMBED AT
15 MIN. BECAUSE ANOTHER
SURGE OF OIL WAS COMING

By Donald L. Miller

General Manager
Position

Witness Chris Johnson

