Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR RUBEAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREA SUNDRY NOT Do not use this form for prop Use "APPLIC) 12: 3 i	Expires: March 31, 1993 5. Lease Designation and Serial No. NMSF - 078828A 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation					
		OTO Harmon					
I. Type of Well Oil Well State of Operator AMOCO PRODUCTION COMPAN	Υ	Attention: Gail M. Jefferson		B. Well Name and No. GALLEGOS CANYON UNT 231 9. API Well No.			
3. Address and Telephone No.		303-830-6	157	300451	1631		
P.O. BOX 800 DENVER, COLORA 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	ADO 80201			10. Field and Pool, or Exploratory Area BASIN DAKOTA			
790 FNL 1450 FEL		28N R 12W	UNIT B	11. County or Parish, State San Juan	New Mexico		
2. CHECK APPROPRIATE	BOX(s) TO INDICA	TE NATURE OF		ORT, OR OTHER DA	ATA		
TYPE OF SUBMISSION Notice of Intent Subsequent Report Final Abandonment Notice	PI C C	bandorment ecompletion Lugging Back asing Repair Itering Casing ther R <u>ecomplete</u>		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water ults of multiple completion on Well Completion	n or Recompletion Report and Log form.)		
13. Describe Proposed or Completed Operations (Clearly state all pertinent markers and zones pertinent to this work.)* AMOCO PRODUCTION COMP. PROCEDURES. IF YOU HAVE ANY TECHNICA JEFFERSON FOR ANY ADMIN	ANY REQUESTS PERM	ISSION TO RECOM	APLETE THIS WE	ELL PER THE ATTACH F (303) 830-4332 OR G			
				DECEI N oct 2 8 and Com	VED 1998 DIV.		
14. I hereby cartify that the foregoing a trip and correct	Oll m		OD ADDAIN CTATE	ACCT	10-20-1998		
Signed Xall M	. Sfirson	Title	SR. ADMIN. STAFF	ASSI. Date	10 20 1000		
(This space for Federal or State office use) Approved by Conditions of approval, if any:		Title		Date			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticious, or fraudulent statements or representations as to any matter within its jurisdiction.

District I PO Bax 1980, Hobbs, NM 88241-1980 District II 811 South First, Artesia, NM 88218 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV

State of New Mexico Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION 2040 South Pacheco Santa Fe, NMC87503 PHI2: 31 M 23

Form C-102
Revised October 18, 1994
Instructions on back
Submit to Appropriate District Office
State Lease - 4 Copies
Fee Lease - 3 Copies

040 South Pack	eco, Santa I	Fe, NM 87505	;			(070 E	And A		AMENDEI	REPOI	
		W	ELL LO	CATIO	N AND	ACR	REAGE DEDI	ICATION P	LAT			
API Number 1 Pool Code 3004511631 79680					le	Kutz Pictured Cliffs, West (Gas)						
'Property Code 'Prope						perty	Name		• Well Number 231			
'OGRID No. 'O 000778 Amoco Procuction Comp					on Compa	ny	Name	* Elevation 5747				
					10 Surf	ace	Location			-		
UL or lot no. B	Section 27	Township 28N	Range 12W	lot ida	Feet from t	tbe	North/South line North	Feet from the 1450	East/West lin		y Juan	
	·	<u> </u>	11 Bot	toin Hol	e Locatio	on If	Different Fro	om Surface	J			
UL or lot no.	Section	Township	Range	lot idn	Feet from t		North/South line	Feet from the	East/West lin	e Coun	ly	
6		OR A	NON-ST.	ANDARD	UNIT HAS	S BE	ON UNTIL ALL EN APPROVED	BY THE DIVI	SION RATOR C ify that the inform plete to the best	ERTIFIC	ATIO!	
								Printed Nam Sr. Adn	Gail M. Jefferson Printed Name Sr. Admin. Staff Asst. Title 10/20/98			
· .		()						18	EYOR CE			

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

January 31, 1966
Date of Survey

Signature and Seal of Professional Surveyor:

James P. Leese

1463

Certificate Number

GCU Well Work Procedure

GCU 231

Date:

10/20/98

Objective:

Recomplete from Dakota to Pictured Cliffs

Pertinent Information:

Location:

NE27-28N-12W

County:

San Juan

State:

New Mexico

Lease:

Well Flac: 98570301

Horizon:

Dak to PC

API#:

30-045-11631 Wayne Peterson

Engr: Phone:

H--(303)795-0171

W-(303)830-4332

Call Tom Feldkamp 303-830-5575 or Wayne Peterson 303-830-4332 in Denver to see if steps 6-7 are necessary.

- 1. Check anchors. MIRUSU.
- 2. Check and record tubing, casing and bradenhead pressures.
- 3. Blow down wellhead, kill if necessary.
- 4. Nipple down wellhead, nipple up and pressure test BOP.
- 5. TOH with tubing.
- 6. TIH with tubing conveyed perforating gun and packer. Set packer 1 jt above interval to be perfed and perforate Lower Dakota as specified.
- 7. Test Lower Dakota and report results to Tom Feldkamp or Wayne Peterson before proceeding. If the Lower Dakota is determined to be uneconomic go to step 8. If it is economic a modified procedure will be prepared.
- 8. PXA Dakota. Set CIBP within 50' of top Dakota perf. Spot 150' cmt plug on top of CIBP.
- 9. Log Pictured Cliffs interval with CBL/GR/CCL to insure zonal isolation across PC.
- 10. Perforate the following interval with 4JSPF, 120 deg. phasing: PC 1526-1554
- 11. Fracture stimulate down casing according to schedule 'A'.
- 12. CO to PBTD.
- 13. TIH with 2 3/8" tbg, rods, and pump. Land 1 joint below perfs if possible.
- 14. RDMO. Hook up to pumping unit and well head compressor.

8-5/8", 24# CSA 366' DV too1 SA 1681' DV tool SA 4348' Perforations: 6023 - 6030' 6043 - 51' 6095 - 6115' 6169 - 79' 2-3/8" tbg @ 6115' 4-1/2", 10.5# CSA 6205' x 1500 sx cmt PBD: 6195' TD: 6205' **Amoco Production Company** SCALE: DRG. Galleogs Canyon Unit No. 231