

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-B1424.

5. LEASE DESIGNATION AND SERIAL NO.

SV 080844-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Callegas Canyon Unit

8. FARM OR LEASE NAME

9. WELL NO.

253

10. FIELD AND POOL, OR WILDCAT

Pinon Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

**SW/4 NW/4 Section 19,
T-28-N, R-11-W**

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

1. GUL
WELL ☒ GAS
WELL ☐ OTHER

2. NAME OF OPERATOR

AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2140' PNL & 875' PNL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5645' RDB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The subject well produced 8 BOPM in March 1969, and produced only gas in April 1969. The well has been shut in since that time, and it is desired to permanently plug and abandon this well in the following manner:

1. Spot 50 sacks cement over perforations at 5564-5546' and squeeze 20 sacks into the formation.
2. Spot 20 sacks from 4300-4044' over bottom of Mesaverde.
3. Spot 20 sacks from 3200-2944' over top of Mesaverde.
4. Spot 10 sacks from 2538-2410' over Chacra.
5. Spot 20 sacks from 1706-1430' over Pictured Cliffs.
6. Spot 20 sacks from 256'-surface.
7. Cut off wellhead, erect PIA marker, and clean up location.

(Cement was circulated to surface on surface casing.)

FEB 10 1973

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Engineer

DATE

February 8, 1973

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.