Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 200

BI	Expires: November 30, 2000								
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS						5. Lease Serial No. SF-078904-A			
Do not use this form for proposals to drill or to re-enter an					6. If Indian, Allottee or Tribe Name				
abandoned well. Use form 3160-3 (APD) for such proposals.						S. I. Lidding / Motors of Thoc Wallie			
SUBMIT IN TRIPLICATE - Other instructions on receive side.						7. If Unit or CA/Agreement, Name and/or No.			
I. Typc of Well ☐ Oil Well Gas Well ☐ Oth	JAN 2008			8. Well Name and No. GALLEGOS CANYON UNIT 281					
2. Name of Operator AMOCO PRODUCTION COM	CHERRY HLAVA E-Mail: Illevacl@bp.com			9. API Well No. 30-045-23706					
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phose No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700			10. Field and Pool, or Exploratory KUTZ WEST PICTURED CLIFFS					
4. Location of Well (Footage, Sec., T				11. County or Parish, and State					
Sec 25 T28N R12W NESW 24			SAN JUAN C	AN JUAN COUNTY, NM					
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE N	IATURE OF	NOTICE, RE	PORT, OR OTH	IER DATA	4		
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent ■	☐ Acidize	☐ Deepe	n	☐ Producti	on (Start/Resume)	□ Wa	ter Shut-Off		
_	☐ Alter Casing	☐ Fractu	☐ Fracture Treat		☐ Reclamation		ll Integrity		
☐ Subsequent Report	☐ Casing Repair	☐ New (Construction	n Recomplete		☐ Other			
☐ Final Abandonment Notice	☐ Change Plans	➡ Plug a	d Abandon		rily Abandon				
	☐ Convert to Injection	to Injection		☐ Water Disposal					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Amoco Production has received your letter dated Dec. 11, 2001 inquiring as to our plan for the above-mentioned well. Amoco requests permission to plug & abandon the subject well per the attached P&A procedure. For technical questions please contact Allen Kutch @ 281-366-7955									
14. I hereby certify that the foregoing is	true and correct. Electronic Submission : For AMOCO PROI	#9840 verified b	the BLM Well ANY, sent to t	Information S he Farmingto	System n				
Name (Printed/Typed) CHERRY HLAVA (NINU Hlava Title AUTHORIZED REPRESENTATIVE									
Signature (Electronic S	Submission) Date 12/20/2001								
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved By			Title		Date	. 1/1	6/02		
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the	Office							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

San Juan Basin Well Work Procedure

Well Name: Version: Date: Repair Type:	GCU 28 #1 12/20/2 Plug an					
Objectives:						
1. P&A enti	re wellbore.					
Pertinent Info	ermation:					
Location:	Sec 25 T28N R	I2W		Horizon:	Pictured Cliffs	
County:	San Juan			API#:	30-045-23706	
State: New Mexico Lease:				Engr: Phone:	Allen Kutch	
Well Flac:	88648801			Priorie.	(281)366-7955	
Lease Flac:	190381			SAP	X7-	
Formation To	ps: (Estimated fo	rmation tops)				
Nacimento:	(·····	Menefee:			
Ojo Alamo:	500		Point Lookout:			
Kirtland Shale			Mancos Shale:			
Fruitland:	1408		Gallup:			
Pictured Cliffs			Graneros:			
Lewis Shale: Chacra:	1882		Dakota:			
Cliff House:			Morrison:			
Olin Flouse.						
Bradenhead ¹	Test Information	:				+
Test Date:		bing:	Casing:	ВН:		
Time BH	CSG	INT	CSG	_		
5 min						
10 min					·	
15 min						

GCU 281 P&A.DOC

Comments:


Plug and abandonment procedure

- 1. Contact Federal and State agencies prior to starting repair work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM 505-599-8907).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 4. Blow down well and kill well, if necessary, with lease water.
- 5. ND wellhead. NU BOP's.
- 6. POOH with 2-3/8" tbg.
- 7. TIH with CIBP on tbg. Set CIBP at 1650'.
- 8. Spot 12 sack cmt plug 1500' 1650' to isolate the PC.
- 9. Spot 12 sack cmt plug 1300' 1450' to isolate the Fruitland.
- 10. Spot 12 sack cmt plug 400' 550' to isolate the Ojo Alamo.
- 11. Spot 12 sack cmt surface plug 0 150'.
- 12. ND BOP. Cut off wellhead and casing. Weld on 1/2" steel plate and PXA marker.
- 13. Provide workorder to Buddy Shaw for surface reclamation.

GCU 281 P&A.DOC Page 2

GCU 281 - Proposed P&A Configuration San Juan County, NM Unit K Section 25 T28N - R12W Run 24

12-20-2001 ATK



PBTD: 1888' TD: 1927'