Form 3160-5 (June 1990)

DE BUF

35

UNITED STATES	FORM APPROVED
PARTMENT OF THE INTERIOR REAU OF LAND MANAGEMENT	Budget Bureau No. 1004-013 Expires: March 31, 1993
TEAU OF LAND MANAGEMENT	

SUNDRY NOTICES AND Do not use this form for proposals to drill or t Use "APPLICATION FOR PE	to deepen or reentry to a different reservoir.	SF 080844 A 6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Other		8. Well Name and No.
2. Name of Operator	Attention:	Gallegos C U 182E 9. API Well No.
AMOCO PRODUCTION COMPANY 3. Address and Telephone No.	Lois Raeburn	_
P.O. Box 800, Denver, Colorado 80201	(303) 830-5294	3004524864 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Basin Dakota
•		11. County or Parish, State
1525 FSL 1740FWL Se	ec. 19 T 28N R 11W	San Juan New Mexico
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, F	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly state all pertin	Recompleti	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water ort results of multiple completion on Well Completion or lon Report and Log form.
Amoco Production Company request permis	DECETY OF MAR - 6 1995 OUL CON. DIV.	
14. I hereby certify that the foregoing is true and correct Signed A Company of Endered or State of figures and correct (This was a far Endered or State of figures)	Title Business Ass	sistant _{Date} 02-20-1995
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	APPROVED
Title 18 U.S.C. Section 1001, makes it a crime for any person knowing representations as to any matter within its jurisdiction.	ly and willfully to make to any department or agency of the United Stat	les en selecticitous, or fraudrent statements or

PXA Procedures Gallegos Canyon Unit 182E

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 3/8" tbg. Run CBL to determine TOC. RIH with tbg and cement retainer. Set retainer at 5000'. Test casing integrity to 500#. Squeeze perfs at 5050' to 6168' with 624.636 cuft cement. Pull out of retainer and spot cement to 4900' with 13.425 cuft cement.
- 4. Depending on where TOC is be sure there is 100' inside and outside casing at the following locations:

Mesa Verde at 3054'
Chacra at 2476'
Pictured Cliffs at 1532'
Fruitland Coal at 1248'
and 493 to surface to get all water zones.
(est 408.85 cuft cement outside and 85.020 cuft cement outside)

- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

GALLEGOS CANYON UNIT #182E LOCATION -19K 28N 11W SINGLE DK ORIG.COMPLETION - 12/B1 LAST FILE UPDATE - 2/92 BY CSW

