

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMSF - 077966
2. Name of Operator AMOCO PRODUCTION COMPANY		6. If Indian, Allottee or Tribe Name
3a. Address P.O. BOX 3092 HOUSTON, TX 77079		7. If Unit or CA/Agreement, Name and/or No.
3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700		8. Well Name and No. GALLEGOS CANYON UNIT 236E
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 14 T28N R12W SWSW 1010FSL 1190FWL <i>13</i>		9. API Well No. 30-045-26270
		10. Field and Pool, or Exploratory BASIN DAKOTA
		11. County or Parish, and State SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

On 3/12/01 Amoco Production requested permission to continue the shut-in status for this well pending our well by well review to determine if an attempt could be made to restore it back to production, either in the existing zone or uphole and avoid premature abandonment of possible reserves. That request was approved 3/30/01.

We have completed the well review & find no further potential exists for this well.

Please approve our request to P&A the subject well per the attached plugging procedure.

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #10155 verified by the BLM Well Information System
For AMOCO PRODUCTION COMPANY, sent to the Farmington**

Name (Printed/Typed)	CHERRY HLAVA <i>Cherry Hlava</i>	Title	AUTHORIZED REPRESENTATIVE
Signature	(Electronic Submission)	Date	01/23/2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By	Title	Date
	<i>PE</i>	<i>2/8/02</i>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	
	<i>FFO</i>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ****

San Juan Basin Well Work Procedure

Well Name: GCU 236E
Version: #1
Date: 1/21/2002
Budget: DRA
Repair Type: Plug and abandonment

Objectives:

1. P&A entire wellbore.

Pertinent Information:

Location:	Sec 14 T28N R13W	Horizon:	Basin Dakota
County:	San Juan	API #:	30-045-26270
State:	New Mexico	Engr:	Allen Kutch
Lease:		Phone:	(281)366-7955

Formation Tops: (Estimated formation tops)

Nacimiento:		Menefee:	
Ojo Alamo:	320	Point Lookout:	
Kirtland Shale:	440	Mancos Shale:	
Fruitland:	1195	Gallup:	5355
Pictured Cliffs:	1675	Graneros:	
Lewis Shale:		Dakota:	6300
Chacra:		Morrison:	
Cliff House:	3265		

Bradenhead Test Information:

Test Date:	Tubing:	Casing:	BH:	
Time	BH	CSG	INT	CSG
5 min				
10 min				
15 min				

Comments:

Plug and abandonment procedure GCU 236E


1. Contact Federal and State agencies prior to starting P&A work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM 505-599-8907).
2. Check location for anchors. Install if necessary. Test anchors.
3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
4. Blow down well and kill well, if necessary, with lease water.
5. ND wellhead. NU BOP's.
6. POOH with 2-3/8" tbg, visually inspecting.
7. TIH with CIBP on tbg. Set CIBP at 6200' to abandon the DK perms.
8. Spot 12 sack cmt plug 6050' – 6200' to isolate the DK.
9. Spot 12 sack cmt plug 5250' – 5400' to isolate the GP.
10. Spot 12 sack cmt plug 3100' – 3250' to isolate the MV.
11. Spot 19 sack cmt plug 1500' – 1750' to isolate the PC / Fruitland.
12. Spot 12 sack cmt plug 250' – 400' to isolate the Ojo Alamo.
13. Spot 12 sack cmt surface plug 0 – 150'.
14. ND BOP. Cut off wellhead and casing. Weld on 1/4" steel plate and PXA marker.
15. Provide workorder to Buddy Shaw for surface reclamation.

GCU 236E - Proposed P&A Configuration
San Juan County, NM
Unit M Section 14 T28N - R13W
Run 25

1-21-2002
ATK

KB: 12'

Proposed 12 sack cmt
plug 250' - 400'



Proposed 12 sack
cmt sfc plug 0 -
150'

8-5/8" 11.6# K55 @ 322'
w/ 325 cf cmt,
circulated cmt to sfc

Proposed 19 sack cmt
plug 1500' - 1750'

Proposed 12 sack cmt
plug 3100' - 3250'

DV tool @ 3236'
W/ 983 cf cmt
circulated cmt to sfc

Proposed 12 sack cmt
plug 5250' - 5400'

Proposed 12 sack cmt
plug 6050' - 6200'

Proposed CIBP @ 6200'

4-1/2" 11.6# K55 @ 6494'
w/ 870 cf cmt (1st stage)

DK perms:

6296' - 6308'
6356' - 6400'

PBTD: 6454'
TD: 6494'