UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

<u>/</u>	٠.				12
5. LEASE	te	-	-		
SF 078046		:	4.	to also	
	_				

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME		
1. oil gas X other	Hughes		
2. NAME OF OPERATOR	9. WELL NO. 3E		
Tenneco Oil Company	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR	Basin Dakota		
P. O. Box 3249, Engelwood, CO 80155 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
below.)	Sec. 20, T29N R8W		
AT SURFACE: 985' FNL 1000' FEL "A"	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico		
	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15 ELEVATIONS (SHOW DE KOD AND WO)		
	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	THE TAX THE PARTY OF THE PARTY		
TEST WATER SHUT-OFF X REC			
	1 0 1981 / KILLIVA		
REPAIR WELL	(NOTE: Report results of multiple completion or zone		
PULL OR ALTER CASING U. S. GEO	DEOGICAL SURVEYOR FORM 9-33 .) JUL 14 1981		
MULTIPLE COMPLETE	NCTAN N M		
ABANDON*	OIL CON. COM.		
(other)	DIST. 3		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertinent	lirectionally drilled, give subsurface locations and t to this work.)*		
6/26/81 - RIH w/tbg to PBTD. Circ hole clean w/DI-HCL @ 7725'. POOH w.tbg. Perf'd Dakota w/3-7480-85', 7489-7506', 7585-88', 7670-77', 7683-8 holes. Break down perfs @ 1450 PSI. Estb rate: Acidize w/2100 gals 15% HCL and 153 balls. Ball basket. Frac w/90,000 gasl 30# XL gel and 1% KC	-1/8" csg gun @ 2 JSPF as follows: 38', 7701-05', 7716-26'. 51' 102 38 BPM @ 3000 PSI. ISIP 900 PSI. off complete. Ran wireline junk CL water and 160,000# 20/40 sand.		
AIR: 67 BPM, AIP: 2900 PSI ISIP: 1300 PSI. 15	min SIP: 1000 PSI.		
6/27/81 - RIH w/tbg and SN. Tag SD @ 7710'. Co @ 7498'. Remove BOP and install WH. Kick well RDMOSU.	to PBTD w/N2 and foam. Land tbg around w/N2. Flwg well to CU		
Subsurface Safety Valve: Manu. and Type	Set @ Ft.		
18. I hereby certify that the foregoing is true and correct			
SIGNED TOTALE ASST. DIV. Adm	1.Mgr.date7/6/81		
(This space for Federal or State off			
APPROVED BY TITLE TOTAL CONDITIONS OF APPROVAL, IF ANY:	DATE		

*See Instructions on Reverse Side

JUL 09 1981

ALUBERTER FOR RECORD

