Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM P.O.Box 2088 30-045-08770 DISTRICT II Santa Fe. New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE X DISTRICT III STATE 1000 Rio Brazos Rd., Aztec, NM 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Jaquez Gas Com A 1. Type of Well: OTHER 2. Name of Operator 8. Well No. Attention AMOCO PRODUCTION COMPANY Mary Corley 9. Pool name or Wildcat P.O. Box 3092 77253 281-366-4491 Houston TX **Basin Fruitland Coal** 4. Well Location G 1620 **NORTH** 1900 **EAST** Unit Letter Feet From The Line and Feet From The Line 29N Section 9W San Juan Township Rang **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5648' RKB 11. Check Appropriate Box to Indicate Nature of Notice Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any 8/9/1999 MIRUSU ND WH, NU BOP. TOH w/TBG. TIH w/CIBP & set @ 6523'. Test to 500# - Held OK. Set 1st plug 6523' - 6272' w/19 SXS CLS B Neat CMT. Set 2nd plug @ 5738' - 5531' w/16 SXS CLS B Neat CMT. Set 3rd plug @ 3911' - 3704' w/16 SXS CLS B Neat CMT. TOH w/TBG & SDFN. RU & ran CBL log. Shot 2 SQZ holes @ 2250'. TIH w/CMT retainer & set @ 2137'. Unable to circ. to surface w/WTR. RU & pump 400 SXS CLS B Neat CMT. No circ. Sting out of retainer & spot 50' of CMT on top of retainer. RU & reran CBL after CMT job. Shot 2 SQZ holes @ 1600'. Pumped 10 BBLS & got circ. TIH w/TBG & TOH LD TBG on float. RU CMT & fill CSG & backside intermediate w/CMT from 1600' to surface w/15 BBLS CLS B Neat CMT. Cutoff wellhead & weld on P & A marker, SDFN. 8/13/99 RDMOSU @ 9:00 hrs. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Sr Business Analyst 10-11-1999 SIGNATURE TITLE DATE Mary Corley TYPE OR PRINT NAME TELEPHONE NO. 281-366-4491 (This space for State Use) DEPUTY OIL & GAS INSPECTOR, DIST. #3 ORIGINAL SIGNED BY E. VILLANUEVA DATE OCT 20 1990 APPROVED BY \_ CONDITIONS OF APPROVAL, IF ANY