

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

PROJECT DESIGN NO. 1001-0145
Expires August 31, 1985
5.1. AREA DESIGNATION AND SERIAL NO.
Jicarilla Tribal 519

SUNDRY NOTICES AND REPORTS **RECEIVED**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for each project.)

OCT 04 1985

1. ☐ OIL
WELL ☐ GAS
WELL ☒ OTHER

2. NAME OF OPERATOR

Amoco Production Co.

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, N M 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

790' FSL X 1670' FEL

6. WELL IDENTIFICATION NAME

Jicarilla Tribal 519

7. WELL NO.

1

10. OTHER END TOOL, OR VILDCAT

Under Gallup-Basin Dakota

11. GEO. SURV. OR TOWN AND
RANGE OR AREA

SW/SE Sec 18, T30N, R2W

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RE, GR, etc.)

7424' GR

12. COUNTY OF WELL 13. STATE

Rio Arriba New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENT TO:

ABANDON WATER SHUT-OFF

REEL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOTING OR ACIDIZE

ABANDON*

REEL WELL

CHANGE PLANS

(Other) Casing Change

FURTHER ACTION OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log forms)

16. PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any
work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all intervals and zones perforated
in this work.)*

Amoco Production Co. requests approval to change the casing
program for the above referenced well as follows:
Surface casing from 13 3/8" to 9 5/8" 32.3# H-40
to a depth of 500' rather than 300'.
The hole size will be 12 1/4" rather than 17 1/2".

RECEIVED

OCT 15 1985

OIL CON. DIV.
DIST. 3

I hereby certify that the foregoing is true and correct

SIGNED

B.D. Shaw

TITLE

Adm. Supervisor

DATE

10-2-85

(This space for Federal or State review use)

**APPROVED
AS AMENDED**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 10 1985

M. MILLENBACH
AREA MANAGER

*See Instructions on Reverse Side

NMOCC