

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. NM-0468128
2. NAME OF OPERATOR Southland Royalty Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1520'N, 1500'E	8. FARM OR LEASE NAME Hagood
14. PERMIT NO.	9. WELL NO. 2
15. ELEVATIONS (Show whether OP, RT, GL, etc.)	10. FIELD AND POOL, OR WILDCAT W. Kutz Pic. Cliffs
	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 34, T-29-N, R-13-W N.M.P.M.
	12. COUNTY OR PARISH San Juan
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Other) ☐ (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is intended to plug & abandon this well in the following manner:

MOL&RU. NU BOP. POOH laying down 1" siphon string. PU 2 3/8" work string. TIH, circ. wellbore clean w/9# mud, 25 sx gel/100 bbls. Spot 30 sx plug (35 cf) from TD to 1450'. POOH. WOC. TIH, tag cmt. and record top. Spot 12 sx (14 cf) plug 1255-1155' to cover Fruitland top. POOH. RU wireline unit, perf 4 holes @ 205'. Circ. down 5 1/2" with 55 sx (65 cf) up through bradenhead, leaving 30 sx (35 cf) in annulus covering Ojo Alamo top at 155' and 8 5/8" shoe @ 103'; and 25 sx (29.5 cf) in 5 1/2" from 205' to surface. Cut off wellhead. Install dry hole marker.

RECEIVED
DEC 18 1987
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Peggy L. Cook TITLE Drilling Clerk

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED

DATE 12-10-87

DEC 16 1987

John Shultz
MANAGER
OIL CON. DIV.

*See Instructions on Reverse Side