(June 1990) DEPARTMEN	TED STATES NT OF THE INTERIOR LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals		NM - 0468128 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Soil Well Gas Well Other 2. Name of Operator Para mount Petroleum 3. Address and Telephone No. 1000 Rio Brazos Rd. 4. Location of Well (Footage, Sec., T., R., M., or Survey D 1020/Na 1890/E Sec. 34,	A ZTEC, NM 87410 334-6178 escription)	8. Well Name and No. 16 Central Total 9. API Well No. 30045 07738 10. Field and Pool, or Exploratory Area Total Callup 11. County or Parish, State
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	San Juan, NM RT, OR OTHER DATA
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface locations and measured and true vertice	DECETION	any proposed work. If well is directionally drilled.
	0[][] GOT D[[V]	

14. I hereby certify that the foregoing is true and correct

Signed NMOCU Contract Title Date

Title Date

Title Date

MAY 2 | 1998

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

TRIPLE P WELL SERVICE, INC.

CENTRAL TOTAH #16

RIG 6

START 4/14/98

END 4/16/98

- 1. No tubing
- 2. Pickup and run in hole with 157 joints (4945'). Circulate well clean.
- 3. Pump 60sx, 71cf, 4945' to 4153'.
- 4. Tag plug @ 4211'. Perforate @ 3148'.
- 5. Displace and balance from 3148' to 2948'. 50sx, 59cf
- 6. Displace and balance from 1584' to 920'. 50sx, 59cf
- 7. Perforate @ 368'. Mix and pump 120sx, 141cf. Did not circulate to surface.
- 8. Tag cement @ 351'. Set cement retainer @ 252'. Perforate @ 241'. Circulate 90sx, 106cf to surface.