Form 9-331 (May 1963)

WELL X

NAME OF OPERATOR

FRACTURE TREAT

REPAIR WELL

(Other)

SHOOT OR ACIDIZE

UNITED STATES SUBMIT IN TRIPLICATE* (Other instructions on reverse side)

Form approved, Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

4-20-603-2168 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NDRY NOTICES	AND	REPORTS	ON	WELLS

SUN (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

5790' KB

GEOLOGICAL SURVEY

Navajo 7. UNIT AGREEMENT NAME NW Cha Cha 8. FARM OR LEASE NAME

Humble Oil & Refining Company 3. ADDRESS OF OPERATOR

GAS WELL

P. O. Box 120, Denver, Colorado 80201

OTHER

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

NE SE (1980' FSL, 780' FEL) Sec. 27

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO.

10. FIELD AND POOL, OR WILDCAT Cha Cha Gallup 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

NW Cha Cha Unit

9. WELL NO.

43-27

San Juan

Sec. 27-29N-14W NMPM 12. COUNTY OR PARISH | 13. STATE <u>N</u>._M.

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PULL OR ALTER CASING TEST WATER SHUT-OFF MULTIPLE COMPLETE ABANDON*

CHANGE PLANS

WATER SHUT-OFF FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF: REPAIRING WELL ALTERING CASING

ABANDONMENT* (Norz: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-30-72 Spot 15 sack cement plug from 5346-5246 Spot 15 sack cement plug from 4400-4300

Spot 40 sack cement thru hole @ 1650. Top of cement inside casing @1550. 10-2-72

10-5-72 Shot off casing @ 1280. Pulled casing.

Spot 50 sack cement plug from 1300' to 1150'. 10-6-72 Spot 40 sack cement plug from 252-152.

Installed regulation dry hole marker with 10 sack cement plug 0-30'. 10-9-72 Cleaned location for inspection. Intervals between plugs filled with gelled mud.

CC: 2-New Mexico Oil Conservation Commission

1-Minerals Supervisor-Navajo Tribe

1-Midland



8. I hereby certify that the foregoing is true as		DATE TO THE STATE OF THE STATE
(This space for Federal or State office use)	TITLE	DATE