

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
80-045-12000

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
E 10786

7. Lease Name or Unit Agreement Name

STATE AG <003259>

8. Well No.
29

9. Pool name or Wildcat
BLANCO MESAVERDE <72319>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
CONOCO INC. <005073>

3. Address of Operator
20 Festa Drive Ste 100 W. Midland, TX 79705

4. Well Location
Unit Letter N : 1190 Feet From The SOUTH Line and 1850 Feet From The WEST Line
Section 38 Township 29 N Range 10 W NMPM SAN JUAN County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING
OTHER:
SUBSEQUENT REPORT OF:
REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB
OTHER: RECOMPLETE TO MESAVERDE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-12-94 MTRU. POOH W/ PRODUCTION EQUIPMENT. GIH W/ RBP SET @ 5985'. CIRC HOLE CLEAN & TEST CAS & PLUG TO 2500#. POOH. RUN GR-CCL: & OBL FROM 5985 TO 3500'. SHOWS GOOD BOND ACROSS ZONE. POOH. GIH W/ 3 1/8" SELECT FIRE GUNS. PERF W/ 1 JSPT @ 4204, 4206, 4208, 4210, 4212, 4214, 4216, 4218, 4220, 4222, 4224, 4226, 4228, 4230, 4248, 4250, 4252, 4254, 4256, 4260, 4264, 4268, 4286, 4288, 4290, 4296, 4306, 4308, 4310 & 4312.
FRAC W/ 66,564g 30# X-LINK GEL 50% SPECTRA FOAM W/ 155,810# 16/30 ARIZONA SAND. FLUSHED W/ 4200# 20# GEL 50% AGAFOAM.
GIH W/ RBP SET @ 4130'. TEST PLUG TO 2500#. DUMP 2 SX SAND ON TOP.
GIH W/ 3 1/8" GUNS PPER W/ 1 JSPT @ 3824, 3826, 3828, 3876, 3878, 3880, 3882, 3884, 3886, 3888, 3814, 3816, 3818, 3819, 3820, 3880, 3882, 3884, 3886, 3888, 3892, 3894, 3896, 4052, 4054, 4056, 4104, 4106, 4108, 4110, 4112, 4114, 4116, 4118, 4148. POOH W/ PERF EQUIP. FRAC W/ 75,738g 30# X-LINK GEL W/ 30,220# 40/70 ARIZONA SAND & 202,270# 16/30 ARIZONA SAND. GIH CLEAN OUT SAND TO REP @ 4100'. RELEASE PER. POOH. GIH W/ 2 3/8" TBG SET @ 4290'. RETURN WELL TO PRODUCTION IN THE MESAVERDE FORMATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Frank T. Keathly TITLE SR. REGULATORY SPEC. DATE 7-13-94
TYPE OR PRINT NAME FRANK T. KEATHLY TELEPHONE NO. 915-686-5424

(This space for State Use)
APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE JUL 14 1994
CONDITIONS OF APPROVAL, IF ANY: