UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	ices and Reports on Wel	.15	
	(,)	5.	Lease Number SF-078578-A
Type of Well		6.	If Indian, All. or
GAS	_	79070	Tribe Name
	18	19 20 21 22 25	
	50/1	- 4 7.	Unit Agreement Name
Name of Operator	1	AUG 3	
BURLINGTQN		5000	
RESOURCES OIL	& GAS COMPANY 🖂 🔾	6 (4)	
		Der	Well Name & Number
Address & Phone No. of Opera	tor		Howell K #3A
PO Box 4289, Farmington, NM	87499 (505) 326-9700	$\mathcal{L}_{\mathcal{L}}}}}}}}}}$	API Well No . 30-045-21665
5 33 5 5		10	Field and Pool
Location of Well, Footage, S 1630'FSL, 1030'FEL, Sec.15,		10.	Blanco Mesaverde
1630 FSE, 1030 FEE, Sec.15,	1-30-N, K-6-W, MAEA	11.	County and State
			San Juan Co, NM
. CHECK APPROPRIATE BOX TO IN			R DATA
Type of Submission	Type of A		
Notice of Intent	Abandonment	Change of Pl	
	Recompletion	New Construc	
X Subsequent Report	Plugging Back	Non-Routine Water Shut	
Final Abandonment	Casing Repair Altering Casing		to Injection
Final Abandonment	X Other -		20 111,0001011
	n defice		
Describe Proposed or Comp	oleted Operations		
3. Describe Proposed or Comp	oleted Operations		
7-20-00 MIRU. SDON.			
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON.	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO	OH w/2 3/8" tbg	. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. TRD. Rig relea	TIH, tag up @ 5787'. TO		. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. T	TIH, tag up @ 5787'. TO		. ND BOP. NU WH.
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. TRD. Rig releases	TIH, tag up @ 5787'. TO ased.	correct.	
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. TRD. Rig relea	FIH, tag up @ 5787'. TO ased.	correct.	ate 8/7/00 TLW
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. TRD. Rig releases	TIH, tag up @ 5787'. TO ased. e foregoing is true and the fittle Regulator te Office use)	correct.	
7-20-00 MIRU. SDON. 7-21-00 ND WH. NU BOP. TRD. Rig releases 4. I hereby certify that the igned Tammy Wim Sal	FIH, tag up @ 5787'. TO ased. The foregoing is true and the second of t	correct.	ate 8/7/00 TLW

Sm- - Jirill