P.O. Box 579,

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Reseeded

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

PULL OR ALTER CASING MULTIPLE COMPLETE

REPAIR WELL

CHANGE ZONES

ABANDON*

Form 9–331	Budget Bureau No. 42-B1424
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF 078813
GEOLOGICAL SURVEY	6. IF INDIAN ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas W other	Federal
	9. WELL NO.
2. NAME OF OPERATOR	6E
Mesa Petroleum Co.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota, Blanco MV
.O. Box 579, Flora Vista, N.M. 87415	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 6-29-N-11W
below.) 1750/N;805/W	12. COUNTY OR PARISH 13. STATE
AT SURFACE: AT TOP PROD. INTERVAL:	San Juan N.M.
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	-
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5808 GL
PEROPE OF	

OCT 14 1980 OTE: Report results of multiple completion or zone

charge on Form 9-330.)

(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*


RECEIVEL

U. S. GEOLOGICAL SURVEY

FARMINGTON, N. M.

SUBSEQUENT REPORT OF

Reseeded Pipeline right-of-way and location.



*See Instructions on Reverse Side

001191982