Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Evnires: March 31, 1993

,		5. Lesse Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		Sf-047020B
	drill or to deepen or reentry to a different reservoir. FOR PERMIT - " for such proposals	6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well Oll Gee Well Other		B. Well Name and No.
Well Well Other 2. Name of Operator	Attention:	Eaton Com B #1
Amoco Production Company	Pat Archuleta, Room 1205C	9. API Well No.
3. Address and Telephone No.	(202) 020 5217	3004524418
P.O. Box 800, Denver, Colorado 8020	1 (303) 830-5217	10. Field and Pool, or Exploratory Area Blanco Mesaverde/Chacra
4. Location of Well (Footage, Sec., T., R., M., or Survey D.	escription)	11. County or Parish, State
1040'FSL 790' FEL	Sec. 25 T 29N R 11W Unit P	San Juan New Mexico
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
TYPE OF SOBINISSION		
571	Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction Non-Routine Frecturing
Subsequent Report	Plugging Beck Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
Final Abandonment Notice	Other(Note: Rep	Dispose Water ort results of multiple completion on Well Completion or
	Recomplet tate all pertinent details, and give pertinent dates, including estimated date of startin	ion Report and Log form.)
If you have any questions contact l	Dave Smith at (303) 830-4502. DEC 1 2 1333 ODL CORS. DATA. DUST. 6	
14. I hereby certify that the foregoing is true and correct Signed (This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	PROVED 12-04-1996 PEC 0 9 1995 DEC NO. SPECET GER
Title 18 II S.C. Section 1001 makes it a crime for any se	erson knowingly and willfully to make to any department or agency of the United St	ates any false, ficticious, or fraudulent statements or
representations as to any matter within its jurisdiction.	erson knowingly and willfully to make to any department or agency of the United St	

Eaton Com B #1
Orig. Comp. 10/80
TD = 4550', PBTD = 4518'
Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 2 3/8" tbg. RIH with tbg and CIBP #1. Set CIBP #1 at 3966'. Spot 100' cement plug on top of CIBP #1. (22 cuft cement).
- 4. RIH with tbg and CIBP #2. Set CIBP #2 at 2706'. Test csg integrity to 500#. Spot 100' cement plug on top of CIBP #2. (22 cuft cement).
- 5. Run shortstring CBL to determine TOC. Depending on TOC ensure that all three formations are isolated with cement outside of casing.

Pictured Cliff @ 1739' Fruitland @ 1419' and Ojo Alamo @ 530'

- 6. Spot 100' cement plugs required inside of casing (50' above and 50' below formation tops) across the Pictured Cliff, Fruitland, Ojo Alamo and surface (269' to surface) casing. (183 cuft cement).
- 7. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 8. Contact FMC and ship surface equipment to yard or other location per instructions.
- 9. Turn over to John Schwartz for reclamation.
- 10. Rehabilitate location according to BLM or State requirements.