

Submit 3 Copies
To Appropriate
District Office
DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
811 South First, Artesia NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised 1-1-89

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-045-25092
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Northstar Oil and Gas Corp		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 93 Farmington, NM 87499		7. Lease Name or Unit Agreement Name: Davie
4. Well Location Unit letter <u>M</u> : 330 feet from the <u>S</u> line and 330 feet from the <u>West</u> line Section 2 Township 29N Range 15W NMPM San Juan County		8. Well No. 1.
1. Elevation (Show whether DF, RKB, RT, GR, etc.) 5159 G.L.		9. Pool name or Wildcat Meadows Gallup

RECEIVED
MAY 14 1999
OIL CON. DIV.
DIST. 3

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: _____	OTHER: _____

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.

1. Check anchors and prepare location
 2. R.U. workover rig. Kill well if necessary. Nipple up wellhead and BOP.
 3. Pull and inspect existing tubing.
 4. RIH with tubing and packer.
 5. Test casing and acidize Gallup perforations.
 6. Pull packer and re-run tubing with seat nipple.
 7. Drop bumper sub and plunger and hang on to test potential Gallup production.
- Operations are expected to begin within 90 days, but depend on negotiations with landowners.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John C. Corbett TITLE President DATE 5/14/1999
Type or print name John C. Corbett Telephone No. (505) 327-5751

(This space for State use)

APPROVED BY Charlie T. L... TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE MAY 14 1999
Conditions of approval, if any: