

(SUBMIT IN TRIPLICATE)

Land Office Santa FeLease No. SF 070500-AUnit N/A of Sec. 5UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 21, 1956Well No. 1 is located 245 ft. from N line and 850 ft. from E line of sec. 5

N/A Sec. 5 (1/4 Sec. and Sec. No.) 30N (Twp.) 8E (Range) 100W (Meridian)
Blanco (Newman) (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6271 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 99 joints (3231') of 7 5/8" 26.40# 4-55 SS Casing. Landed at 3241. Cemented with 150 sacks. Casing was pressured to 500# for 1 hour with no drop in pressure, after cement set, plug was drilled and hole blown dry with gas. It remained dry and drilling ahead with gas was resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Dalziel-Taylor Oil CorporationAddress P. O. Box 1175Farmington, New MexicoBy M. HowellTitle Dist. Supt.

